



CARTWRIGHT-MOSS HOUSE *Cartwright House*
OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN

PHOTO BY: Elizabeth Woosley, Nashville

DATE: April 1978

NEG: Tn. Historical Commission JUN 5 1979

North facade, view facing southeast

#1 of 11

AUG 1 1979
D O E



CARTWRIGHT-MOSS HOUSE

Cartwright House

OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN

PHOTO BY: Elizabeth Woosley, Nashville

DATE: April 1978

NEG: Tn. Historical Commission

West elevation, view facing east, showing
east chimney before rebuilding

#2 of 11

DOE

AUG 1 1979

JUN 5 1979



CARTWRIGHT-MOSS HOUSE

Cartwright House

OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN

PHOTO BY: Elizabeth Woosley, Nashville

DATE: April 1978

NEG: Tn. Historical Commission

View facing northwest showing south elevation
of 1850s addition and east elevation of
southern part of 1809 building, before
1978 addition

#3 of 11

AUG 1

DOE
1979

JUN 5 1979



CARTWRIGHT-MOSS HOUSE *Cartwright House*
OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN?

PHOTO BY: Robert E. Dalton

DATE: August 1978

NEG: Tn. Historical Commission

East facade facing west, showing rebuilt
east chimney and 1978 addition under
construction

#4 of 11

AUG 1

1979

DOE

JUN 5 1979



CARTWRIGHT-MOSS HOUSE

Cartwright House

OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN

PHOTO BY: Robert E. Dalton

DATE: August 1978.

NEG: Tn. Historical Commission

East facade facing west showing 1978 addition
under construction

#5 of 11

AUG 1

DOE
1979

JUN 5 1979



CARTWRIGHT-MOSS HOUSE

Cartwright House

OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN

PHOTO BY: Robert E. Dalton

DATE: August 1978

NEG: Tn. Historical Commission

South facade facing northwest, showing
1978 addition under construction

#6 of 11

DOE

AUG 1 1979

JUN 5 1979



CARTWRIGHT-MOSS HOUSE *Cartwright House*
OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN.

PHOTO BY: Robert E. Dalton

DATE: August 1978

NEG: Tn. Historical Commission

Main stairway in 1850s addition photographed
during 1978 renovation, showing framing
of 1850s addition and part of 1978
addition under construction

#7 of 11

AUG 1 1979

DOE
JUN 5 1979



CARTWRIGHT-MOSS HOUSE

Cartwright House

OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN

PHOTO BY: Robert E. Dalton

DATE: August 1978

AUG 1 ^{DOE} 1979

NEG: Tn. Historical Commission

Minor stairway (from first floor to second
floor) located in southwest room in 1809
section of house

#8 of 11

JUN 5 1979



CARTWRIGHT-MOSS HOUSE

Cartwright House

OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN

DOE

PHOTO BY: Robert E. Dalton

AUG 1 1979

DATE: August 1978

NEG: Tn. Historical Commission

Minor stairway (from second floor to attic)
located in southwest room in 1809 section
of house

#9 of 11

JUN 5 1979



CARTWRIGHT-MOSS HOUSE

OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN

PHOTO BY: Robert E. Dalton

NEG: Tn. Historical Commission

DATE: August 1978

Southeast corner of northwest room showing
stud extensions to raise ceiling during
1850s rebuilding

#10 of 11

JUN 5 1979

Cartwright House

DOE

AUG 1

1979



CARTWRIGHT-MOSS HOUSE

Cartwright House

OLD DICKERSON PIKE, GOODLETTSVILLE, DAVIDSON
CO., TN

DOE

PHOTO BY: Robert E. Dalton

DATE: August 1978

AUG 1 1979

NEG: Tn. Historical Commission

North and east facades of log smokehouse
with camera facing southwest

#11 of 11

JUN 5 1979