United States Department of the InteriorNational Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received AUG 12 1985 date entered

Continuation sheet Item number 8 Page 6

N. E-297,220; N-5,067,370 O. E-297,220; N-5,067,400 P. E-297,290; N-5,067,400

HARDIN HISTORIC RESIDENTIAL DISTRICT

Period of Significance: 1907 - 1930

Areas of Significance: architecture, exploration/settlement

Acreage: approximately 8 acres Ownership: multiple ownership

Status: occupied

Accessible: yes, restricted Present Use: residential

Physical Description:

The Hardin Residential District contains primarily single-family residences, the primary styles being simple vernacular and the Craftsman. Some of the vernacular houses have been modified, but retain sufficient integrity of materials, design, and craftsmanship to allow one to see the simple gabled or hipped forms of the first houses that were built in Hardin to provide basic shelter without an attempt to embrace the tenets of any particular style. Typical modifications include asbestos or hardboard siding or applied stucco finish to the exterior walls, enclosed porches, side and rear room and porch additions. A vernacular building has been judged to have retained sufficient integrity to qualify for listing as a contributing structure within the district when it dates from the historic period of significance and has retained the majority of its original historic fabric, detailing, original fenestration, form, and massing, although exterior walls may have been sheathed in non-historic materials.

The predominant early residential style in Hardin was the Craftsman style and it appeared shortly after 1910. Hardin's Craftsman houses exhibit typical elements of the style: one or 1-1/2 story wood frame construction, broad eaves decorated with exposed rafters, and brackets, and wall boards, projecting windows, wood shingle and clapboard siding, dormers, and ample porches -- all arranged in a picturesque manner and set in the midst of a spacious yard. Almost all of the Craftsman style residences within the historic district have retained an extraordinary degree of historic architectural integrity.


Statement of Significance:

The Hardin Residential Historic District is significant because it exhibits two types of residences that clearly reflect Hardin's growth and development and that are distinctive types of residences found in rural agricultural towns of this period in Montana: the vernacular designs built by the first settlers in the community and, more prominently, the Craftsman style which gained clear ascendency in Hardin between 1910 and 1920. The Residential Historic District also contains residences of individuals significant to Hardin's early history including Carl Rankin, who surveyed the townsite and was the first agent for the townsite company, and several of Hardin's early business owners.

NPS Form 10:900-a OMB No. 1024-0018 (3:82) Exp. 10-31-84

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form



Continuation sheet Item number 8 Page 7

The growth of residential neighborhoods in Hardin followed a lop-sided pattern. Although new residential subdivisions were filed with the county very soon after the town's founding and these newly platted areas surrounded the Original Townsite, residential development occurred primarily to the north and east of the commercial district. Further inventory work in Hardin may shed light on the reasons why the residential neighborhoods developed in this manner.

Location, Verbal Boundary Description, and Justification:

The Hardin Residential Historic District is comprised only of those areas within the Hardin Original Townsite survey area which are comprised predominently of residential structures that date from the first two decades of Hardin's existence. This Residential Historic District does not encompass all of the residences in Hardin that are of historic or architectural significance, but is limited to the buildings located within the geographical limits of the survey area. Other blocks of buildings will likely be added to this nomination during the next few years as more neighborhoods in Hardin are inventoried.

Hardin's Residential Historic District includes the following parcels in the Hardin original Townsite: Block 3, Lots 17 and 18; all of Blocks 4-6. The individual properties are Block 15, Lot 3 and Block 15, Lot 4. UTM references for the district are as follows (all UTM's are in zone 13):

- W. E-296,990; N-5,067,290
- L. E-297,050; N-5,067,290
- X. E-297,050; N-5,067,400
- O. E-297,220; N-5,067,400
- Y. E-297,220; N-5,067,510
- Z. E-296,990; N-5,067,510

Location map or building plan with arrow north.

ARCHITECTURAL	_ INVENTO	RY Site #	
Legal Description: Original Tow		t 5	
Address: 408 N. Custer At	76.		· · · · · · · · · · · · · · · · · · ·
Ownership: name: Robert Guy	er		
		Historic Name: Guy Hous	
	110274	Date of Construction: 18 De additions 191 Architect:	C • 1903 ☐ documented
	NORTH	Builder Andrew Rouss	eau
		Original Owner: Andrew Ro	
		Original Use: residence	later plumbing shop
	Ž,	Present Use: residence	
	00 S TB	Research Sources:	© city directories 1918, 122
	•	☐ plat records/maps ☑ tax cards	sewer/water permits
FOURTH		 building permit Sanborn maps — dates: 1910 , 	© obituaries 1914,1920
7		Bibliography:	pers: 18 Dec. 1908; r. 1917; 6 Aug.
		6 June 1936;	U, 24 JELL. 1970;

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This $1\frac{1}{2}$ story four-square hipped roof house of brick bearing wall construction has been stuccoed. It has a concrete foundation, two later shed roof dormers, and two brick chimneys, one at the center of the original low-square and one on the rear addition. Window and door openings are arched, and window sash are 10/1 (front) and 8/1 (side) double hung sash. The small front entry canopy has a gabled roof with partially returned eaves, a sylindrical ceiling, and two Tuscan columns. Out-buildings at the rear of the lot include a shed a gabled roof garage, and a car-port.

This house was built by A. Rousseau, a brick mason and contractor. He built many of the brick buildings in Hardin. In 1915, the house was bought by Fred E. Miller, who was Big Horn County's first clerk and recorder. In 1916, the house was occupied by Carl Rankin, who was an early agent for the Lincoln Land Co. In that year he returned to Hardin after an absence of five years.

This building contributes to the Hardin district as a representative of the early residences built in Hardin's first neighborhoods. It is particularly significant because it is one of the oldest surviving houses in Hardin and it housed some important individuals. It may therefore be considered of primary significance.


INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

This building has sustained little alteration and retains a high degree of integrity.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
NameDeloris Luther	Acreage:
Star Rt. Hardin, Mt.	USGS Quad:
Date: June 1984	UTM's:

Site #

AIIOIII LOIOIIAL IIIV LIII OIII Site #	
Legal Description: Original TownBlock 5so. 33 ft 6" of Lot2	The state of the s
no. 😤 Tot. 3	
Ownership: name: Rick Seder	• . 64
public address: 610 N. Cheyenne	Roll # Frame #



PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This 1½ story Craftsman Bungalow has a concrete foundation, wood frame construction, and a gable roof with wood shingles. There is a large gabled dormer on east. There is an outside brick chimney with corbelled cap on the south. Surviving craftsman detailing include exposed rafters and gable end brackets, and decorative wall boards with a flair at their lower ends to match the flaired roof. Altered details include the full-length craftsman porch, which has been enclosed, and the clapboard siding, which has been covered with wide hardboard siding.

This house began as a parsonage for The Methodist Episcopal Church of Hardin, Mt. in 1919. No finishing work was done to the second floor. In 1936 the partitions from the first floor were removed and developed into a sanctuary for church services. The second floor became a parsonage apartment (complete remodeling details in "First Fifty Years" booklet). It was dedicated as the "Hardin Wesley Methodist Chapel" Feb. 25, 1936. In 1955 it was sold to Guy Van Cleve, who had operated a large ranch north of Hardin. Mr. Van Cleve was a state representative from Big Horn County in 1947. He remodeled the house into apartments. He died in 1958. Mrs. Van Cleve sold to Rick Seder in 1982.


This building contributes to the Hardin district as a representative of the early Craftsman residences built in Hardin's first neighborhoods.

INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

This house has been somewhat altered, yet retains its overall integrity as an early residence and as a contributor to the residential streetscape of Hardin.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
Name Deloris Luther	Acreage:
Address: Hardin, Mt.	USGS Quad:
Date: July 1984	UTM's:

MONTANA HISTORICAL AND ARCHITECTURAL INVENTORY | Site



	1	Historic Name:
		Common Name: McDonald House
FOURTH		Date of Construction: was moved onto four estimated dation from 5th St. in 1916 Architect:
J-1	7 [Builder
	NORTH	Original Owner Helen Reeder
		Original Use: Boarding House
	•	Present Use: Private residence
		Research Sources:
		Abstract of title
		☐ plat records/maps ☐ sewer/water permits
	3	☐ tax cards 🔀 obituaries
	8	□ building permit □ biographies X Sanborn maps — dates: 1920
1		Bibliography: Hardin Tri. papers: 22 Sept. 1916; 13 Oct. 1916; obit W.E. Mc-
•	1	Donald, Tri. 7 Dec. 1962; obit Mary
		McDonald, Tri. 21 June 1979. Death
Location map or building plan with	arrow north.	Cert. Henry Beck, 1982.

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This yellow clapboard craftsman house with green asphalt shingles has concrete foundation, central brick chimney with corbelled cap, and over hanging eaves with brackets. Most windows are double hung. The screen porch covers the full width of the front. The house was moved from somewhere on 5th St. to this location in 1916. A frame garage of drop siding, with one bay and asbestos shingles sits at the rear of the lot. An interesting feature of this and other Hardin garages is the addition put on later for added length of cars, just enough to cover hood.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance.			
from 5th St. and leased it as a boar McDonald, arrived in Hardin in 1927. Ave. where Ben Franklin now is. This building contributes to the Har	He had a grocery store on Center		
INTEGRITY: Assess the degree to which the structure/site, and su property.	urrounding area accurately convey the historical associations of the		
This house has been somewhat altered as an early residence and as a control of Hardin.	, yet retains its overall integrity ributor to the residential streetscape		
INFORMATION VALUE: Explain how the extant structure/site may tion.	demonstrate or yield information about its historic use or construc-		
	2		
FORM PREPARED BY: Deloris Luther	GEOGRAPHICAL INFORMATION:		
NameHardin, Mt.	Acreage:USGS Quad:		
Date: July 1984	UTM's:		

Location map or building plan with arrow north.

ARC	HITECTURAL	INVENTO	RY Site #	
Address:	original Town- 320 N. Crow Ave.		t 2	
Ownership:				Roll # Frame #
	FOURTH	394	Historic Name: Peck House Common Name: Kirschent Date of Construction: 1917 Architect: Builder:	mann House
			Original Owner Ralph Peo Original Use: residence Present Use: residence	ek
		NOSTH	Research Sources: A abstract of title Part Part A plat records/maps tax cards building permit Part A sanborn maps - dates: 1920 Part Part Bibliography:	56

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

July 1984.

This Craftsman style bungelow has a wood shingled hip and valley roof and sits on a concrete foundation. The house of wood frame construction with a stucco finish. The front porch, which has a brick veneer base and brick rectangular piers, appears to have originally been open. The roof is puncuated by two central brick chimneys with corbelled caps, one towards the east and one towards the west, and two hipped roof dormers, one on the south side and one on the north.

Ehis was the Peck House built between 1917 and 1920. Mrs. (Josephine Ackerman) Peck was an early teacher and leader in founding the Carnegie Library. Mr. Ralph Peck, a 1906-1907 homesteader of north valley, later had a transfer business. The house was sold to John Knodel in 1952. He came from North Dakota in 1936, a retired farmer, later carpenter, he died at the age of 92. In later years the house was a rental property until 1978 when the house was purchased by John Kirschenmann, son-in-law of John Knodel. Kirschenmann retired from farming in 1961 and later became a school custodian. Now retired, they still own the house.


This building contributes to the Hardin district as a representative of the early Craftsman residences built in Hardin's first neighborhoods.

INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

This building has sustained little alteration and retains a high degree of integrity.

FORM PREPARED BY: Deloris Luther	GEOGRAPHICAL INFORMATION:
Name	Acreage:
Address: Hardin, Mt.	USGS Quad:
Date: July 1984	UTM's:

ARCHITECTURAL INVENTORY Site #	
Legal Description: Original TownBlock 3Lots 17 & 18	and a
Address: 419 N. Custer	
Ownership: name: Big Horn County Library	→ 32A → 53
□ private □ public address:	Roll # Frame #



PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This building is a one story building on an elivated base, with a central entry pavillion. The entry was modified from the original neo-classical design to a flat roofed brick entry. The building covers two partial lots and is rectangular in shape. It is built of dark red brick, in running bond. The roof has a front parapet and over pavillion only. The cornice is metal with brackets. Windows, replaced at the time of remodeling, are 1/1 in basement, double hung. Sinage is integral, in raised metal applied over entrance "Carnegie County Library". South side entrance to basement area has cement stairs and pipe railing. The rear entrance to basement meeting room is similar.

Library services for Hardin people began in Aug. of 1912 with the donation of 100 books. One room of the W.E. Fearis home became the library with Mr. or Mrs. Fearis in charge. To provide money for the purchase of more books a membership drive was held, with the amount of \$1.00 being charged. \$91.00 was raised. At the city election in 1914 a .05 mill levy was voted for the library and proceeds were to be used for room rental and to obtain about 800 more books. The need for more room became apparent and in May of 1914 the Carnegie Corp. was contacted and asked for a building. They were denied. The library committee did not give up and by March 1916 the Carnegie Corp. would make a \$7,500 donation provided the city would furnish a site and \$750 for annual maintenance. After considerable correspondence between the County Commissioners and Carnegie Corp. a gift of \$15,000 was forth-coming from the Carnegie Corp. The Commissioners appointed a three-man building committee: Dr. W.A. Russell, Earnest Adler and Percy Wilcox, who later resigned and was replaced by A.H. Rousch. C.L. Pruitt was selected as the architect and plans were submitted and adopted. Percy Wilcox was awarded the building contract. Construction began Apr. 5, 1918. On May 10, 1918 the cornerstone was laid, containing a sealed metal box with one punny. one dime. one quarter, one thrift stamp, one postage stamp, a brief history of the Hardin Library. history of Big Horn County and the history of the town of Hardin and the current issue of the Hardin Tribune. In July W.E. Fearis was named as County Librarian, and in Dec. of 1918 the finishing touches were put on the building. In June of 1919 the dedication of the library was held. The building and it's history are recorded in the E rel Hardin papers through the vears and has remained unchanged until the remodeling in the recent years. The library contributes to the district as a representative of the

INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

The library lost integrity when the original neo-classical main entry was remodeled to it's present composition. However, other major dec-orative elements remain intact.

typical Carnegie library donations made throughout the nation.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:	
Name_ Jackie Redding	Acreage:	
Address: Biq Horn. Mont.	USGS Quad:	
Date: June 1984	UTM's:	

MONTANA HISTORICAL AND

ARCHIECIURAL INVENTURY Site#	
Legal Description: Original TownBlock 4Lot 9	
Address: 411 N. Crow Ave.	
Ownership: name: Alfred E. Sargent	+26A +27
□ private address: 411 N. Crow Ave.	Roll # Frame #

			Historic Name: <u>√arr</u> ∈	n House
}		_	Common Name:	
			Date of Construction: 191	1
			Architect:	
7			Builder A. Roussea	เน
704			Original Owner: A. Rou	sseau
2			Original Use: reside	nce
			Present Use: residence	
1			Research Sources:	
			abstract of title	city directories
1 1		1 1	plat records/maps	sewer/water permits
		1 1	☐ tax cards	🛣 obituaries
		4 <u>}</u>	☐ building permit	☐ biographies
ı			☐ Sanborn maps — dates:	
سرطيده	H FOURTH		Bibliography: Hardin	Tri. papers: 18 Feb.
NORTH POURT				29; 14 Feb. 1936;
				en, Tri. 5 May 1947;
7				p.214; Conversation,
Loc	ation map or building plan with arrow north.)]	Bonnie Warren B	eary-June 1984

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This 1½ story rectangular, porch fronted house has interesting gables with full eave returns. The house is wood frame with brick veneer featuring brick simulation quoins at the corners. Double hung 1/1 wind-ows are set in openings with brick sills and headers. The porch has a hipped roof supported by four Tuscan columns. The house has recently been modified with the addition of knotty pine gable ends and porch base.

A brick garage sits at the back of the lot. However, it is not the structure built by Rousseau in 1910, the year before the house was built. HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance.

A. Rousseau was a brick mason. In 1910 he built a big brick barn on the back of this lot, lived in it that winter and built the house on front in 1911. W. B. Warren purchased the house in 1916. He was a banker and large area farmer. Mrs. Warren ran what she called Pine Lodge in the barn in back of the house. It was torn down in early 40's. The Pine Lodge bricks were used for building the garage now standing.

This building contributes to the Hardin district as a representative of the early residences built in Hardin's first neighborhoods.

INTEGRITY: Assess the degree to which the structure/site, and surfounding area accurately convey the historical associations of the property.

This house has been somewhat altered, yet retains its overall integrity as an early residence and as a contributor to the residential street-scape of Hardin.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
Name_ Deloris Luther	Acreage:
Address: Hardin, Mt.	USGS Quad:
Date:July 1984	UTM's:

Site #

ANOTHIE CIONAL INVENTORY Site #	
Legal Description: Original TownBlock 4Lot 6	N. A. S.
Address: 406 N. Custer AVe.	· · · · · · · · · · · · · · · · · · ·
Ownership: name: George & Eva Miller	The state of the s
public address: 406 N. Custer Ave.	

			Historic Name:	
1	1		Common Name: Miller I	House
				e stimated X documented
		d	Architect:	
		Costex	Builder	
		3	Original Owner Sarah Trub)y
		V	Original Use: residence	
			Present Use: residence	
			Research Sources:	
		A	🔀 abstract of title	☐ city directories
]			☐ plat records/maps	sewer/water permits
			🔀 tax cards	🔀 obituaries
			□ building permit	biographies
			Sanborn maps — dates: 1910,	1914, 1920
	FOURTH	NOETH	Bibliography:	
	·		"Lookin' Back" p. 1	37-138
]		/	Lammers family.	
l	Location map or building plan with ar	row north.		

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This $1\frac{1}{2}$ story frame gabled roof cottage sits on a concrete foundation and has asphalt shingle roof. It features an enclosed front porch. The house has 1/1 double hung sash windows and asbestos siding. There is a small rear kitchen addition. The garage at the rear of the lot is of new construction.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. Sarah Truby, original owner, lived with two sons, one of whom was a trader with Indians. In 1917 title was transfered to Susan Lammers, wife of B.J. Lammers. He was known for well drilling which has been carried on through the family to his grandson Joe today. This building contributes to the Hardin district as a representative of the early residences built in Hardin's first neighborhoods. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property. This house has been somewhat altered, yet retains the overall integrity as an early residence and as a contributor to the residential streetscape of Hardin. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. FORM PREPARED BY: **GEOGRAPHICAL INFORMATION:** Deloris Luther Name_ Acreage:_ Hardin, Mt. Address: USGS Quad:_ July 1984 Date:_ UTM's:_

MONTANA HISTORICAL AND

FOUKTH

ARCHITECTURAL INVENTO	RY Site#
Legal Description: Original TownBlock 4e-Lo Address: 403 N. Crow Ave. Ownership: name: Lillian Trene Noblett	→23A →24
public address: 319 D. Barry, Glendive, Mt.	59330 Roll # Frame #
	Historic Name: Cleland Cottage Common Name: 1910
Noth	Research Sources:

X abstract of title

plat records/maps

city directories sewer/water permits

obituaries biographies

☐ building permit

Bibliography: Back" p. 271 (Yera Cleland)

Location map or building plan with arrow north.

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This one story brick house has been stuccoed. It has a wood shingle gable roof and 3/1 double hung windows set in arched openings. The early wooden front porch evident in the Sanborns has been replaced by a small centrally located, gabled, enclosed, front vestibule. A rear stuccoed addition continues the original building lines including the gable ridge and eave lines.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. This house is known as the Cleland House. A.R. Cleland and his estate owned this lot from 1910 to 1914, so it is speculated that he was the original owner and that it was built during that period. The house has had numerous subsequent owners. This building contributes to the Hardin district as a representative of the early residences built in Hardin's first neighborhoods. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property. This house has been somewhat altered, yet retains its overall integrity as an early residence and as a contributor to the residential streetscape of Hardin. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. FORM PREPARED BY: GEOGRAPHICAL INFORMATION: Deloris Luther Name_ Acreage:_ Hardin, Mt. Address:_ USGS Quad:_ July 1984 Date:_

MONTANA	HISTO	RICAL	AND
ARCHITECT	URAL	INVEN	TORY

Location map or building plan with arrow north.

ARCHITE	CTURAL INV	ENTO	RY Site #	
	riginal TownBl	ock 4I	ot 8	
	. Crow Ave.			
	Charles L. Willi	ams		→ 25A → 2
private public address:	405 N. Crow Ave	•		Roll # Frame #
			Historic Name:	
1 5			Common Name:	
		1.		estimated
		1 1	Date of Construction: bef	ore 1920
		1 1	Architect:	
MOAS		1 1	Builder.	
1 \$		1 1		
0		1 1	Original Owner:	
		1 1	Original Use: reside	
		1 1	Present Use: residen	ce
		1 1		
		1 1	Research Sources:	☐ city directories
	1	1 1	plat records/maps	sewer/water permits
	<u> </u>	1 1	☐ tax cards	☐ obituaries
-		-+ +	☐ building permit	☐ biographies
			Sanborn maps — dates: 197	- 0
Noeth	Fourth		Bibliography: Conversation,	Mabel Simmons-July 1984.
\neg \mid		7 1		, JOT•

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This T-shaped wood frame house with intersecting gables sits on a concrete foundation. It has a shed roof porch at the southwest corner. The house has been modified with metal siding, new front fixed and 1/1 double hung windows and new 4x4 porch supports and brick planter which extend across the entire front. Side windows appear to be original.

HISTORICAL SIGNIFICANCE: Justify how the persons, importan and surrounding area lend the property significance.	t events, and of historical patterns associated with the structure sits
According to the Sanborn Map, this has had numerous owners and it is no This building contributes to the Har of the early residences built in Har	t know who the original owner was.
INTEGRITY: Assess the degree to which the structure/site, and su property.	urcounding area accurately convey the historical associations of the
This house has been somewhat altered as an early residence and as a contract scape of Hardin.	, yet retains its overall integrity ibutor to the residential street-
INFORMATION VALUE: Explain how the extant structure/site may tion.	demonstrate or yield information about its historic use or construc-
	demonstrate or yield information about its historic use or construc-
	demonstrate or yield information about its historic use or construc-
	demonstrate or yield information about its historic use or construc-
tion.	
FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
FORM PREPARED BY: Name Deloris Luther	GEOGRAPHICAL INFORMATION: Acreage:
FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:

MONTANA HISTORICAL AND

ARUTHEUTURAL INVENTURY Site #		
Legal Description: Original TownBlock 4Int 4		
Address: 410 N. Custer Ave.		
Ownership: name: Bloyde D. Carper	→ 32A	→ 53
The services of the services o	Roll #	Frame #

		-	Historic Name:		ell House	
1 1	1	1	Common Name:	Russell	House	
			Date of Construction	on:1914	<u> </u>	estimated documented
	\	- 1	Architect:			
	X #		Builder:			
		}	Original Owner:	Dr. J.A.	Russell	W
			Original Use:	ome and o	ffice	
			Present Use:	esidence		*
			Research Sources:			1016 10
T			Abstract of title		City directories	
			☐ plat records/maps tax cards		sewer/water pe	rmits
					biographies	
المرمان ومع		ı	☐ building permit ☐ Sanborn maps — d	1920		
FOURTH	Nozav	3	Bibliography:	din paper	s: 11 Aug	. 1915:
			7 Apr. 192	2; 26 Nov	1937; 1	May
			194 1; 27 F	eb. 1969;	20 Apr.	
			"Lookin'			
Location map o	or building plan with arrow north.	1	Ru	ssell fam	ı⊥у .	

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This one story craftsman cottage, built in 1914, is of rectangular shape, with a formed concrete foundation, and white clapboard siding, and green trim. The house has a gable roof. It has an unfinished basement. The screen front porch has a gabled roof and is offset to the south. Both the porch and the main gable roofs feature typical Craftsman details such as gable and brackets and decorative wall boards. Windows, double hung on the side and fixed in the front, are original. The interior was remodeled in 1941, but the exterior has not been altered except for the handi-capped stair extension on the front stoop. It has a 18x18' garage built in 1941, with drop siding, gable roof, and concrete slab-on-grade.

Dr. Wilson Adams Russell, original owner of this house, was a physician in Hardin for many years. He served as health officer for federal, state, county, city and school authorities. He was also an authority on the Custer Battle. He was responsible for placing the marker at the site of the Hay Corral fight south of St. Kavier. Dr. Russell, during his long stay in Hardin, had performed many philanthropic acts not generally known to the public. Among them he made it possible for several young men and women of Big Horn County to obtain a college education and provided a home and schooling for deserving children whose parents were unable to give them these advantages. He was always ready to help the unfortunate.

This building contributes to the Hardin district as a representative of the early Craftsman residences built in Hardin's first neighborhoods.

INTEGRITY: Assess the degree to which the structure/site, and surçounding area accurately convey the historical associations of the property.

This building has sustained little alteration and retains a high degree of integrity.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
Name Deloris Luther	Acreage:
Address: Star Rt., Hardin, Mt.	USGS Quad:
Date: May 29, 1984	UTM's:

MONTANA HISTORICA ARCHITECTURAL INVE		
Legal Description: Original TownBlock	4Lo	ot 1 & No. 10' of Lot
Address: 424 N. Custer		
Ownership: name: Robert Williamson private public address:		
		Historic Name: Fish House
	- 1	Common Name:
	l	Date of Construction: 1930 s ⊠ estimated ☐ documented
		Architect:
AFTH		Builder: Wilbur Fish
		Original Owner_Wilbur Fish
NO BYH	1	Original Use: Home & Contractor Wood Shop.
Now.		Present Use: residence
	Ì	Research Sources:
	ł	abstract of title
		☐ plat records/maps ☐ sewer/water permits
N		☐ tax cards ☐ obituaries ☐ building permit ☐ biographies
STEP	1	Sanborn maps — dates: 1920
		Bibliography: Conversation-Jeanne Fish, wid. of
		Gerald Fish and Dauin-law of
•	•	Wilbur Fish, June 1984.
Location map or building plan with arrow north.		

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This single frame white dwelling sits high on concrete foundation with gable roof of composition shingles. It has 3/1 windows on each side of the central front door. It has a full basement and an unfinished attic. Chain link fence surrounds the house. The old garage has gable shingle roof, one bay facing 5th St. and a center brick chimney with corbelled cap. All windows are double hung. Grey with white trim. Garage is grey, gable roof, one bay facing 5th St.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. William Hackney bought this lot from the Catholic Church and built the old garage on the rear of the lot about 1919. Wilbur Fish built this home for his family in about 1930. He was a contractor who first arrived in Hardin 1917 to design and build the new Boyum and English Lumber Yard. The house was in the Fish family from 1931 to 1973. The house and garage contribute to the Hardin district as representative of later construction practice during Hardin's development. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property. This building has sustained little alteration and retains a high degree of integrity. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construc-**FORM PREPARED BY: GEOGRAPHICAL INFORMATION:** Name Deloris Luther Acreage:_ Address: Star Rt., Hardin, Mt. USGS Quad:___ July 1984 UTM's:__ Date:

ARCHITECTURAL INVENTORY Site #	41
Legal Description: Original TownBlock 4So. 40' of Lot 2	(A T
No. 10' of Lot 3	
Ownership: name: Hardt's Inc.	-
☐ private □ public address:	+ 31A + 32

Original Owner. Original Use: Present Use: Research Sources: A plat records/maps sewer/water permits a tax cards obituaries building permit biographies Sanborn maps - dates: 1914, 1920 Bibliography:	FIFTH	_		□ estimated ☑ documented
			Original Owner:	

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This brick building with a flat roof has two store fronts, one of which (south) has had its central door closed off. Each store front features a central door opening flanked by plate glass windows with a transom panel of glass block over the entire assembly. The rear of the building has had several (at least two) concrete block additions.

This building is on the 1920 Sanborn. No information has been found about the sheet metal works or paint and paper store shown on Sanborn. In 1925 Midwest Electric opened a gas station and electrical supply house in this building run by Frank Dornberger. This building also at one time had a Willys automobile business run

This building contributes to the Hardin district as a representative of the early commercial buildings constructed along Hardin's business district.

by J.W. Bullis.

INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

This building has sustained little alteration and retains a high degree of integrity.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
Name_ Deloris Luther	Acreage:
Address: Star Rt., Hardin, Mt.	USGS Quad:
Date: July 1984	UTM's:

MONTANA HISTORICAL AND

AKCHII	ECTURAL INVE	NIO	Site #
	Original TownBlock Custer Ave. Hardt's Inc.		
T	Custer.		Historic Name:
Loca	ation map or building plan with arrow north.		•

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This one story wood frame stucco house has a wood shingle gable roof, double hung windows, and a brick chimney with corbelled cap. There is a small addition on the south side.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. According to the Sanborns, this house was built between 1910 & 1914. The lot was owned during that period by the Montana Catholic Church. The history of the Catholic Church in Hardin indicates that this building was probably the first church built by the Catholics. Before it was remodeled as a residence, it had a cross and steeple. The building next served as a plumbing shop for F.G. Hatch who bought the property in 1917 and moved his business into this house in 1918. This building contributes to the Hardin district as a representative of the early residences built in Hardin's first neighborhoods. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property. This house has been somewhat altered, yet retains its overall integrity as an early residence and as a contributor to the residential streetscape of Hardin. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. **FORM PREPARED BY: GEOGRAPHICAL INFORMATION:** Deloris Luther Acreage:_ Address: Star Rt., Hardin, Mt.

USGS Quad:__

UTM's:__

Date: July 1984

MONTANA HISTORICAL AND


ANCHITECTURAL INVENTO	Site #	
Legal Description: Criginal TownBlock 5Lo Address: 410 N. Crow Ave. Ownership: name: Kathryn E. Parks private address:		Roll # Frame #
Location map or building plan with arrow north.	☐ plat records/maps ☐ tax cards	☐ city directories ☐ sewer/water permits ☐ obituaries ☐ biographies
PHYSICAL DESCRIPTION: Describe present appearance of structure noting additions, alterations, and changes in materials. Discuss significant processing the present appearance of structure in the present appearance	•	ith it's original appearance,

This rectangular Craftsman style bungalow has wood shinglessiding from the concrete foundation to the window sills, clapboard siding from the concrete foundation to the window sills, Clapboard Siding from the sills to the window headers, and wood shingle siding above the headers (including the gable ends). Craftsman detailing includes exposed rafters and roof beams, decorative wall board and a small projecting window on the north side. The house appears to have a full length porch across the front of the house under the main gable. However, while the side is a screened porch, the south side is actually an enclosed sun room.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance.			
The Weirs, original owners of this store, Weir & Co. Golden Rule Store. in 1967. Kathryn Parks bought the ho	house, operated a general merchandise Marie Weir taught school, retiring ouse in 1983.		
This building contributes to the Har of the early Craftsman residences by	din district as a representative wilt in Hardin's first neighborhoods.		
	*		
INTEGRITY: Assess the degree to which the structure/site, and s property.	urrounding area accurately convey the historical associations of the		
This house has been somewhat altered as an early residence and as a contractape of Hardin.	, yet retains its overall integrity ributor to the residential street-		
INFORMATION VALUE: Explain how the extant structure/site may			
tion.	demonstrate or yield information about its historic use or construc-		
	demonstrate or yield information about its historic use or construc-		
	demonstrate or yield information about its historic use or construc-		
	demonstrate or yield information about its historic use or construc-		
	demonstrate or yield information about its historic use or construc-		
	demonstrate or yield information about its historic use or construc-		
FORM PREPARED BY:	demonstrate or yield information about its historic use or construc-		
FORM PREPARED BY: Name Deloris Luther			
FORM PREPARED BY: Name Deloris Luther Address: Hardin, Mt.	GEOGRAPHICAL INFORMATION:		
FORM PREPARED BY: Name Deloris Luther	GEOGRAPHICAL INFORMATION: Acreage:		

MONTANA HISTORICAL AND ARCHITECTURAL INVENTORY | Site

Original Town--Block 6--Lot 6 & south 1/2 Lot 5 Legal Description:___ Address: 304 N. Crow Ave. Ownership: name: Alice Kogalshak □ private address: 304 N. Crow Ave. Roll # Frame #



PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This rectangular one-story frame house has a concrete foundation and asbestos siding. All windows are 3/1 except 4 lites in gable of porch. There is a central chimney on the west end addition. The original house, as built by Carl Rankin, had a hipped roof. It was altered by contractor W.S. Fish in 1927 to its present gabled form.

Construction in 1907. This was the second house to be built in Hardin. Carl Rankin, first owner, assisted in the initial survey of the Hardin townsite. As agent of Lincoln Land Co. he sold the first lots in Hardin. This man went on to be mayor of the town in 1940-1946 and again in 1955. He died in 1962. A.L. Mitchell, second owner was Hardin's first mayor. Gwen F. Burla, third owner, was a Hardin banker and state senator from Big Horn County. Jack Kogolshak, whose widow is the present owner, ran at various times Joyland Motel, Arcade Bar, Hill Tavern, Stockman Bar and Cafe, played banjo, accordian, fiddle and organ at many old time dances in Hardin and Big Horn County. He died in June 1984. His widow Alice is still in the house.

This building contributes to the Hardin district as a representative of the early residences built in Hardin's first neighborhoods.

INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

This house has been somewhat altered, yet retains its overall integrity as an early residence and as a contributor to the residential street-scape of Hardin.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
Name Deloris Luther	Acreage:
Address: Hardin, Mt.	USGS Quad:
Date: July 1984	UTM's:

Location map or building plan with arrow north.

Site #

X Sanborn maps — dates:__

Bibliography: "Lookin' Back" p. 2

1914, 1920

Hardin Tri. papers: 6 May 1913; 8 Oct. 1926; 7 Jan. 1927. 25 Sept. 1952 obit. S.A. Howell; 7 Mar. 1968 obit. Ola

Maddox. Conversation, Henry Ruegamer

ANOTHIEGIONAL INVENTO	Site #	Y The state of the
Legal Description: Original TownBlock 6lot Address: 310 N. Crow		10 tr :m = 5
Ownership: name: Regional Community Services private public address: 240 S. 8th WBillings, Mt	for Developmentally Disabled 59101	Roll # Frame #
	Historic Name: Howell Hous Common Name: Group Home	
	Date of Construction: 1913 Architect: Lyle Bros Builder: Lyle Bros	☐ estimated ☑ documented
HOEAH	Original Owner E. A. Howell Original Use: Private res	
	Present Use: Group Home Research Sources:	
THED	☐ plat records/maps	☼ city directories 19/8☐ sewer/water permits☒ obituaries

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This large $1\frac{1}{2}$ story rectangular house features a bay window facing south. It sits on a concrete foundation, has a glassed in porch, a brick outside end chimney with corbelled cap and another bay is on north side of house. It has overhanging eaves with exposed brackets, rafters and wall boards. Most windows have double hung aluminum storms. There is a fire escape extending from upstairs window on the south side. A shed dormer faces Grow Ave. (east). The roof is gable with asphalt shingles. Exterior walls are clapboard while the front porch and its piers are sheathed in wood shingles.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. This house was built by E.A. Howell in 1913. E.A. Howell was vice-president and cashier of the first bank in Hardin. He died in Billings in 1952, after leaving Hardin in 1927. Other owners included John & Hilda Kopriva, co-owners of the Hardin Mercantile Co.; Dan (lawyer & state senator) &Ola (secretary for the Campbell Farming Corp. for 40 years) Maddox; and E.W. (Bill) Christiansen (Lt. Governor under Tom Judge 1972-1976). Regional Community Services for Developmentally Disabled now has house for a group home. This building contributes to the Hardin District as a representative of the early Craftsman residences built in Hardin's first neighborhoods. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the This building has sustained little alteration and retains a high degree of integrity. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construc-FORM PREPARED BY: **GEOGRAPHICAL INFORMATION:** Name Deloris Luther Hardin Address: USGS Quad:_

UTM's:_

July 1984

Site #

		The same of the sa	
T	Doll #	Eromo #	

324 N. Crow Ave. Address. Ownership: name: Richard G. & Leslie J. Wynkoop

Legal Description: Original Town--Block 6--Lot 1

private address: 324 N. Crow	Roll # Frame #
Fourth North	Historic Name: Corwin House Common Name: Date of Construction: 1913
Location map or building plan with arrow north.	

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This 12 story Craftsman residence is basically a square building with various projecting wings. The house sits on a concrete foundation and has a wood shingled hip and valley roof with slightly flaired eaves. The roof is punctuated by a central brick chimney with a corbelled cap and by two hipped dormers, one on the south and one on the east. The east dormer has the same flaired eaves and each has a pair of twelvelight hopper windows. All windows in the place are 1/1 double hung. The main body of the house has clapboard siding and the dormers are sheathed in wood shingles. Other than the addition of aluminum storm windows, the house has not been altered on it's exterior. There is a one-car garage at the rear of the lot.

This house was built by G.F. Corwin, when his daughters went to school in Hardin from his ranch North of town, where he was a prominent stockman. He moved to Martinsdale. The home was sold to E.L. Kelley a banker. Kelleys sold to Ray and Dorothy Morissette, owners of the Purple Cow and Morrissette Ins. Dorothy is a retired school teacher. In 1973 Harry Mosby, auto mechanic bought the house and sold to Richard Wynkoop in 1981, the manager of Safeway Store, who still owns it. This building contributes to the Hardin district as a representative of the early Craftsman residences built in Hardin's first neighborhood.

INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property.

This building has sustained little alteration and retains a high degree of integrity.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
Name Deloris Luther	Acreage:
Address: Hardin, Mt.	USGS Quad:
Date: July 1984	UTM's:

Location map or building plan with arrow north.

ARCHITECTURAL INVENTO	RY Site #	
Legal Description: Original TownBlock 4N. Address: 416 N. Custer Ownership: name: Hardts Inc. private address:	10' of lot 3	ROIL#
FIFTH NOZAM	Historic Name: Common Name: Sally's Hai Date of Construction: Architect: Builder: Trnest Adler Original Owner: Original Use: Plumbing sho Present Use: Beauty shop. Research Sources: Abstract of title plat records/maps tax cards building permit Sanborn maps — dates: Bibliography:	☐ estimated

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

The outside of this building was remodeled in 1984. It included the addition of a featureless store front and a false mansard wood shingle roof. The original square pilasters either side of building, topped by corbelled caps are still in place. The remodeling eliminated a metal cornice over a narrow transom panel, central recessed entry and large plate glass windows. The north side wall with its brick archediwindow openings is intact. The front of the building houses a beauty shop and an apartment is in the rear.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance.

This building at various times had a plumbing shop run by F.G. Hatch, later run by Matt R. Calderwood. Mrs. Calderwood ran a gift shop in the office. Lora Del Peden ran a beauty shop and had apartments added on in 1940. Dater it housed the office of Dr. E.W. Haaby (1955-1968), Pauley's Day Care Center (1968-1971), music store in 1973, and a second hand store for a short time. Atapresent it is a beauty shop called Sally's run by Sally Schmidt and owned by Hardts Inc.

Since being remodeled in 1984, this building has become an intrusive element in the Hardin district. However, it could again be a contributing structure if the store front were restored.

INTEGRITY: Assess the degree to which the structure/site, and surçounding area accurately convey the historical associations of the property.

This building has lost its integrity due to store front remodeling.

INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction.

FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:
Name Deloris Luther	Acreage:
Address: Star Rt., Hardin, Mt.	USGS Quad:
Date: July 1984	UTM's:

Location map or building plan with arrow north.

AR	CHITEC	CTURAL INVE	ENTO	RY Site #	
Legal De	440 17	ginal TownBlock 5th St. (Corner			to a second
	nip: name:	irst Methodist Ch			+28A +29
1	HOZTH	EIFTH	11	Historic Name: Common Name: Method: Date of Construction: 195 Architect: Sushing & 1 Builder: George Original Owner: church Original Use: church	Destinated Governmented Gove
	CEOM			Research Sources: A abstract of title plat records/maps tax cards building permit Sanborn maps — dates: Bibliography: The First Fift	□ city directories □ sewer/water permits □ obituaries □ biographies ty Years of the thurch" 1914-1964.


PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This rectangular brick church was built with face brick in stack bond. It has a gable roof and a brick tower with cross near the main entry the the northwest corner.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. The official opening of this church was 18 July 1954. On June 18, 1956 a consecration service was held. This was the third move for the Methodists, from the Masonic Temple basement to parsonage referred to as the Van Cleve house then to the new brick church. This building is compatable with the Hardin downtown district, but it does not contribute to its significance. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property. This building is of recent construction. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construc-FORM PREPARED BY: **GEOGRAPHICAL INFORMATION:** Deloris Luther Name_ Acreage:__ Star Rt., Hardin, Mt. Address: USGS Quad:___ July 1984 Date:

Site #

AITOITILGI OITAL III V LII I OITI Site #	
Legal Description: Original TownBlock 4Lot 10	
Address: 413 N. Crow	
Ownership: name: First Methodist Church	
public address: c/o Judith NelsonHardin	Rom



PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This single frame house sits on a concrete foundation and has a gable roof of composition shingles, cedar shingle siding, and 2 double hung and fixed windows. There is a one bay garage at the rear of the lot.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. Built in 1955 for parsonage for the minister of the First Methodist Church, this house was used for that purpose until the present Rev. Mills moved into another home. The house is now rented until such time it will again be used as a parsonage. This building is compatable with the Hardin downtown district, but it does not contribute to its significance. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property. This building is of recent construction. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construc-**FORM PREPARED BY: GEOGRAPHICAL INFORMATION:** Deloris Luther Name Acreage:_ Star Rt., Hardin, Mt. Address: USGS Quad:__ July 1984 Date: UTM's:_

Site #


Legal Description: Original Town-Block 5-Lot 6


Address: 205 W. 4th (corner 4th & Crow)

Ownership: name: Richard Dorn & Fred Call Sr. 67%

private address: Treasure State Title Service Inc. 33%

Roll#





PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This one story concrete block office building, on a concrete foundation, has a false mansard roof with wood shakes.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. This building was constructed for Clarence Belue, atty. He shared part of office space with Dr. Downing, D.D.S. until Downing built his own building. Upon his return in 1981 to Hardin Dr. Daniel Gebhardt, M.D. opened his practice, selling to Richard Dorn and Fred Call Sr. in 1983. Dorn and Call sold 33% to Treasure State Title Service Inc. in Apr. 1984. This building sits on the site of Hardin's first public school. This building is an intrusive element. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property. N/A INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. FORM PREPARED BY: **GEOGRAPHICAL INFORMATION:** Deloris Luther Name Acreage:_ Address: Hardin, Mt. USGS Quad:___ July 1984 Date:_ UTM's:__

Site #

Legal Description: Original Town-Block 5-Lot 1 & No. 16'6" of Lot 2


Address: 424 N. Crow Ave.

Ownership: name: A.F. A.M., St. John's Lodge #92



□ private address: c/o Sam Denny, Hardin

Roll # Frame #



PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

Indian who owned plot was Barbara Yellow Weasel. The Masonic Hall was built in 1938 upon the 1916 foundation of the Methodist Episcopal "basement church". This old foundation is still visible. The stucco upper level has a hipped roof and a projecting pavilion at the east end. A stuccoed arched arcade extends along the south side.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. In 1916 the Methodist Episcopal Church of Hardin constructed a basement, roofed and furnished it for conducting church services, planning to build a church on top one day. This never was done. They sold to A.F. A.M. St. John's Lodge #92 in 1938. The Masons put the present building on top. They still own it today. This building is compatable with the Mardin downtown district, but it does not contribute to its significance. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the This building has sustained little alteration and retains a high degree of integrity. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction. FORM PREPARED BY: **GEOGRAPHICAL INFORMATION:** Deloris Luther Acreage:_ Star Rt., Hardin, Mt. Address: USGS Quad:_ June 1984 Date: UTM's:_

MONTANA HISTORICAL AND

Location map or building plan with arrow north.

Site #	

ARCHITECTURAL INVENTO	RY Site#	
Legal Description: Original TownBlock 5Lo Address: 406 N. Crow Ave. Ownership: name: Joe F. Feller private address: 406 N. Crow Ave.	t 5	Roll # Frame #
FOURTH NOTAL	Historic Name: Common Name: Date of Construction: unlmown Architect: Builder: Original Owner: Original Use: Present Use: residence Research Sources: Abstract of title plat records/maps tax cards building permit Sanborn maps — dates: Bibliography:	☐ estimated ☐ documented

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This rectangular gabled roof house has wood shingles and sits on a concrete foundation. It has beveled lapped siding and a/1 double hung windows. Rear entries have been added on both sides of the rear of the house. This house does not appear to be the dwelling that appears on this site in the 1920 Sanborn.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance.				
This house appears (architecturally) or 1930's. No historical record has date. This building is compatable wi neighborhoods, but since its constrube said to be contributing.	been found for its construction the Hardin residential			
·				
INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the property. This building has sustained little alteration and retains a high degree of integrity.				
INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construction.				
· · · · · · · · · · · · · · · · · · ·	demonstrate or yield information about its historic use or construc-			
· · · · · · · · · · · · · · · · · · ·	demonstrate or yield information about its historic use or construc-			
· · · · · · · · · · · · · · · · · · ·	demonstrate or yield information about its historic use or construc-			
FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:			
FORM PREPARED BY: NameDeloris_Tuther	GEOGRAPHICAL INFORMATION: Acreage:			
FORM PREPARED BY:	GEOGRAPHICAL INFORMATION:			

Site #

Legal Description: Original Town--Burlington right of way on Crow Ave. and Railroad St.(only one available)

Address: 206 W. RR ST.

Ownership: name: Gerald F. Beckman

private address: West of Hardin



CRAMPORTO	NOZTH
	Location map or building plan with arrow north.

Historic Name: Occident	Elevator	
Common Name: Bowman 's		
	y 1912	
Architect:		
Builder:		
Original Owner. Russell	Milling Co.	
Original Use: Elevator		
Present Use: Elevator		
Research Sources:		
abstract of title	🕱 city directories	
plat records/maps	sewer/water permits	
💢 tax cards	obituaries	
☐ building permit	☐ biographies	
Sanborn maps — dates:		
Bibliography: Tri. paper	s: 19 July 1912;	
2 Aug. 1912; 27 Oc	t. 1912; 18 Apr.	
1913; 19 May 1916;		
Dec. 1918; 30 July	1920: 10 JULY 1959	

PHYSICAL DESCRIPTION: Describe present appearance of structure/site, then contrast and compare that with it's original appearance, noting additions, alterations, and changes in materials. Discuss significant architectural features.

This, building was built in 1912. Elevator runs parallel to the railroad tracks to the south. Truck ramp runs between the elevator and the office on the north side. It is of wood cribb construction on a concrete foundation with corrugated metal siding. The office is of wood frame with lapped siding and a combination gabled flat roof. It has fixed windows on north and east and a conventional door on the east and two sliding doors on the north. To the north of the west truck ramp is hollow clay tile building. The elevator has three large cylindrical storage bins to the east.

HISTORICAL SIGNIFICANCE: Justify how the persons, important events, and/or historical patterns associated with the structure/site and surrounding area lend the property significance. This building was built in 1912 and was associated with Russell Milling Company. Soon thereafter it was sold to the Occident Elevator Co. First manager was J.S. Tupper in 1913. In 1916 there was a fire in the cupola. Insurance covered damage of \$3,000. 1945-1946 improvements included office and display room. 1948 a steam roller plant was installed along with storage for steam rolled grain. A 1950 annex added a capacity of 40,000 bushels. Occident Elevator is significant as a visual symbol of Hardin's reason for being-as a railroad shipping point of agricultural products. INTEGRITY: Assess the degree to which the structure/site, and surrounding area accurately convey the historical associations of the The Occident Elevator has changed little since it was constructed. with the exception of the late 1940's additions which are compatable in scale materials, and use with the original. INFORMATION VALUE: Explain how the extant structure/site may demonstrate or yield information about its historic use or construc-**FORM PREPARED BY: GEOGRAPHICAL INFORMATION:** "Babe" Rosie A. Butler

USGS Quad:___

UTM's:

Box 5--Big Horn, Mt. 59010

July 1984

Address:_

Date: