



Name: The Carlton David Pepper Farm

Location: County Road 469, near Georgetown, DE

Photographer: Dick Carter

Date: Sept., 1978

Location of Negative: Hall of Records, Dover, DE

Description: View of front of farmhouse from southwest showing most recent (1840's) wing at left.

Photograph Number: One of eight

SEP 24 1979

AUG 13 1979

Sussex County



Name: The Carlton David Pepper Farm
Location: County Road 469, near Georgetown, DE

Photographer: Dick Carter

Date: Sept. 1978

Location of Negative: Hall of Records, Dover, DE

Sussex County

Description: View of front of house. 1840's section are three bays at left. 1820's portion is right two bays of two story section and one and a half story section at right.

Photograph Number:

Two of eight

SEP 24 1979

AUG 13 1979



Name: The Carlton David Pepper Farm

Location: Road 469, near Georgetown, DE

Photographer: Dick Carter

Date: Sept. 1978

Location of Negative: Hall of Records, Dover, DE

Sussex County

Description: View of rear of house from northwest showing
one story rear wing.

Photograph Number: three of eight

AUG 13 1979

SEP 24 1979



Name: The Carlton David Pepper Farm

Location: County Road 469 near Georgetown, DE

Photographer: Dick Carter

Date: Sept. 1978

Location of Negative: Hall of Records, Dover, DE

Description: View of rear of brick milkhouse and rear end of farmhouse showing 1930's kitchen (right), 1 1/2 story section and point where original chimney was removed

Photograph Number: in 1977.

Sussex County

SEP 24 1979 ■ FOUR OF EIGHT AUG 13 1979



The Carlton David Pepper Farm

Name:

County Road 469 near Georgetown, DE

Location:

Photographer: Dick Carter

Date: Sept. 1978

Location of Negative: Hall of Records, Dover, DE

Sussex County

Description: View of original mantelpiece and closed
in fireplace in first floor room of
original one and a half story section
of house.

Photograph Number: Five of eight.

SEP 24 1979

AUG 13 1979



Name: The Carlton David Pepper Farm

Location: County Road 469 near Georgetown, DE

Photographer: Dick Carter

Date: Sept. 1978

Sussex County

Location of Negative: Hall of Records, Dover, DE

Description: View of panelling and fireplace in 1820's two-story section of house showing enclosed stairway at left. Door on right leads into one-and-a-half story section.

Photograph Number: Six of eight

SEP 24 1979

AUG 13 1979



Name: The Carlton David Pepper Farm

Location: County Road 469 near Georgetown, DE

Photographer: Dick Carter

Date: Sept. 1978

Location of Negative: Hall of Records, Dover, DE

Description: View of farm buildings at rear of house.

Left to right: early 19th cent. granary; early 20th century corn crib; mid-19th century log corn crib; early 20th cent. shed, and late 19th cent. barn.

Photograph Number:

Seven of eight

SEP 24 1979

AUG 13 1979

Sussex County



Name: The Carlton David Pepper Farm

Location: County Road 469 near Georgetown, DE

Photographer: Dick Carter

Date: Sept. 1978

Location of Negative: Hall of Records, Dover, DE

Sussex County

Description: View of outbuildings including granary at left, early 20th century corn crib in center, and 19th century log corn crib at right.

Photograph Number: Eight of Eight.

SEP 24 1979

AUG 13 1979