



John Wiard House

Burlington, CT

B. Clouette Photo, 7/79

Negative with Connecticut Historical Commission

Hartford, CT

Main (south) facade, view northeast

FEB 23 1982

1



John Wiard House

Burlington, CT

B. Clouette Photo, 7/79

Negative with Connecticut Historical Commission

Hartford, CT

FEB 23 1982

East facade, view west

2



John Wiard House

Burlington, CT

B. Clouette Photo, 7/79

FEB 23 1982

Negative with Connecticut Historical Commission

Hartford, CT

FEB 20 1982

Detail, moldings around door and under eave 3



John Wiard House

Burlington, CT

B. Clouette Photo, 7/79

Negative with Connecticut Historical Commission

Hartford, CT FEB 23 1982

Interior, east front room, view northwest 4



John Wiard House

Burlington, CT

FEB 23 1982

B. Clouette Photo, 7/79

Negative with Connecticut Historical Commission

Hartford, CT

Interior, kitchen, view southwest

5



John Wiard House

Burlington, CT

B. Clouette Photo, 7/79

Negative with Connecticut Historical Commission

Hartford, CT

FEB 23 1982

Interior, west front room, view northeast 6



John Wiard House

Burlington, CT

B. Clouette Photo, 7/79

Negative with Connecticut Historical Commission

Hartford, CT FEB 23 1982

Interior, front door lock, view southeast

7



John Wiard House

Burlington, CT

B. Clouette Photo, 7/79

Negative with Connecticut Historical Commission

Hartford, CT

FEB 23 1982

Interior, typical latch (from kitchen), view west

8