

Photo 1 Moses Andrews House Meriden, CT. D. Ransom Photo, 5/78 Negative: Connecticut Historical Commission FRONT FACADE. VIEW SOUTHEAST OCT 2 1978

DEC 1 1978



Photo 2 0CT 2 1978 Moses Andrews House Meriden. CT D. Ransom Photo, 5/78 Negative: Connecticut Historical Commission FRONT DOORWAY. VIEW DEC 1 SOUTH



Photo 3 OCT 2 1978 Moses Andrews House Meriden. CT D. Ransom Photo, 5/78 Negative: Connecticut Historical Commission EAST FACADE. VIEW SOUTH-WEST DEC 1 1978



OCT 2 1978 Photo 4 Moses Andrews House Meriden, CT D. Ransom Photo, 5/78 Negative: Connecticut Historical Commission WEST AND SOUTH FACADES. VIEW NORTHEAST DEC 1



Photo 5 Moses Andrews House Meriden, CT DEC 1 1978 D. Ransom Photo, 5/78-Negative: Connecticut Historical Commission STAIRWAY. VIEW SOUTHEAST




Photo 6 Moses Andrews House Meriden, CT DEC 1 1978 D. Ransom Photo, 5/78 Negative: Connecticut Historical Commission FIREPLACE WALL. VIEW SOUTHWEST OCT 2 1978




Photo 7 OCT 2 1979 Moses Andrews House Meriden, CT D. Ransom Photo, 5/78 Negative; Connecticut Historical Commission THUMB LATCH. VIEW NORTH-EAST DEC 1 1978



Photo 8 OCT 2 1978 Moses Andrews House Meriden, CT DEC 1 1 D. Ransom Photo, 5/78 Negative: Connecticut Historical Commsiion ROOF IRON, VIEW WEST