

Carl V. Kling, 1977 Alabama Historical Commission view of School from northwest Photo number: #1



Carl V. Kling, 1977 Alabama Historical Commission

view of Strudivant Residence (#7) from across street



Summerfield Historic District Summerfield, Dallas County, Alabama

Carl V. Kling, 1977 Alabama Historical Commission

view north along Min Street from around College Street

Photo number: #3



Summerfield Historic District Summerfield, Dallas County, Alabama

Carl V. Kling, 1977 Alabama Historical Commission

view along street near well and School

Photo number: #4



Summerfield Historic District Summerfield, Dallas County Alabama

Carl V. Kling, 1977 Alabama Historical Commission

view west along Marion Road just west of intersection with Persimmon Street

Photo number: #5 **JAN 28 1982**



Summerfield Historic District Summberfield, Alabama, Dallas County

Carl V. Kling, 1977

Alabama Historical Commission

veiw east along Marion Road just
west of Sturdivant Residence (#7)



Carl V. Kling, 1977 Alabama Historical Commission

riew of Sturdivant Residence (#7) from east on Marion Road

Photo number: #7



Carl V. Kling, 1977 Alabama Historical Commission

view west along Marion Road from in front of Sturdivant Residence (#7)

Photo number: #8



Carl V. Kling, 1977 Alabama Historical Commission

view along Marion Road from near section intersection 22, 23, 27, 26

Photo number: #9



Carl V. Kling, 1977 Alabama Historical Commission

view south along unpaved road toward Summerfield Methodist Church (#1)



Carl V. Kling, 1977 Alabama Historical Commission

view east along College Street just east of Main Street



Carl V. Kling, 1977 Alabama Historical Commission

view north along unpaved street toward Summerfield Methodist

Photo number: #12



Carl V. Kling, 1977 Alabama Historical Commission View south along Main Street

Photo number: #13



Carl V. Kling, 1977 Alabama Historical Commission

view west along Centenary Street from Johnson House (#8)

Photo number: #14



Carl V. Kling, 1977 Alabama Historical Commission

view east along Centenary Street just east of Selma-Summerfield Road

Photo number: #15



Carl V. Kling, 1977 Alabama Historical Commission

view north along Main Street showing Sturdivant House (#7) and Johnson House (#8)

Photo number: #16



171

Name & Location: Summerfield Historic District Summerfield, Alabama

Name of Photographer: Carl V. Kling

Date photograph was taken: July 1977

Location of negative:
Archives of Alabama Historical
Commission

View:

Exterior Summerfield Methodist Church(#1)

photo #17



Name & Location:
Summerfield Historic District
Summerfield, Alabama

Name of Photographer: Carl V. Kling

Date photograph was taken:

July 1977

Location of negative:
Archives of Alabama Historical
Commission

View:

Interior Summerfield Methodist Church $(\# \mathcal{L})$

Auto#17a



Name of Photographer: Carl V. Kling

Date photograph was taken: July 1977

Location of negative:
Archives of Alabama Historical
Commission

View:

Exterior of the School-Store-Community Building with well to rear. #29

photo=# 18



Summerfield Historic District Summerfield, Alabama

Name of Photographer:

Carl V. Kling

Date photograph was taken:

July 1977

Location of negative:

Archives of Alabama Historical Commission

View:

Well in foreground and Summerfield Methodist Church in background

19



Summerfield Historic District Summerfield, Alabama

Name of Photographer:

Carl V. Kling

Date photograph was taken; July 1977

Location of negative:

Archives of Alabama Historical Commission

View:

Exterior of the Moore-Pinson-Tate Hudson House (#5)



Name of Photographer:

Carl V. Kling

Date photograph was taken: July 1977

Location of negative:

Archives of Alabama Historical Commission

View:

Interior of the Moore-Pinson-Tate Hudson House showing graining of doors and wainscot and door trim.

20a



Summerfield Historic District Summerfield, Alabama

Name of Photographer:

Carl V. Kling

Date Photograph was taken:

July 1977

Location of Negative:

Archives of Alabama Historical Commission

View:

Exterior of the Sturdivant-Moore-Caine Hodo House (#7)



Summerfield Historic District Summerfield, Alabama

Name of Photographer:

Carl V. Kling
Date photograph was taken:

July 1977 Location of negative:

Archives of Alabama Historical Commission

View:

Fire place of the Sturdivant-Moore-Caine Hodo House

JAN 28 1000

21a



Name & Location: Summerfield Historic District Summerfield, Alabama Name of Photographer:

Carl V. Kling Date Photograph was Taken:

July 1977 Location of Negative:

Archives of Alabama Historical Commission

View:

Entrance Hall of the Sturdivant-Moore-Caine Hodo House



Name & Location:
 Summerfield Historic District
 Summerfield, Alabama
Name of Photographer:
 Carl V. Kling
Date photograph was taken:

July 1977 Location of negative: Archives of Alabama Historic

Archives of Alabama Historical Commission

View: Johnson-Chisolm
Exterior of the Composite Rush
House from the southeast CHT 8)

Photo #22 JAN 28 1982



Summerfield Historic District Summerfield, Alabama

Name of Photographer:

Carl V. Kling

Date photograph was taken: July 1977

Location of negative:

Archives of Alabama Historical Commission

View:

: Jhnsn-Chiselm Exterior of the Lappe D-Ryst House from the southwest, showing doctor's office ∉ κ)

JUT# 23

JAN 2 & 1502



Name of photographer: Carl V. Kling

Archives of Alabama Historical Commission ew: View: Exterior Bishop Andrew-Brady House(11)

Date photograph was taken: July 1977 Location of negative:



Summerfield Historic District Summerfield, Alabama

Name of photographer:

Carl V. Kling

Date photograph was taken: July 1977

Location of negative:

Archives of Alabama Historical Commission View: Parlor of Bishop Andrew-Brady House showing mantle and original floor covering

photo # 24 a JAN 28 1982



Name & Location: Summerfield Historic District Summerfield, Alabama Name of photographer: Carl V. Kling Date photograph was taken: July 1977 Location of negative: Archives of Alabama Historical Commission JAN 2 8 1982 View:

Stair Hall Bishop Andrew-Brady House

Photo # 246



Name & Location:
 Summerfield Historic District
 Summerfield, Alabama
Name of photographer: Carl V. Kling

Date photograph was taken: July 1977
Location of negative: JAN 2 8 1982
Archives of Alabama Historical Commission
View:

Exterior Swift-Moore-Cottingham House (12)



Name of photographer: Carl V. Kling Location of negative:

Date photograph was taken: July 1977 Archives of Alabama Historical Commission LAN 28 1982 View: Stairway Swift-Moore-Cottingham House

#25a



Name & Location: Summerfield Historic District Summerfield. Alabama Name of photographer: Carl V. Kling Date photograph was taken: July 1977 Location of negative: Archives of Alabama Historical Commission

View:
Doorway Swift-Moore-Cottingham House
#7256
JAN 2 8 1982



Name & Location:
Summerfield Historic District
Summerfield, Alabama
Name of photographer: Carl V. Kling

Date photograph was taken: July 1977
Location of negative:
Archives of Alabama Historical Commission
View:

Parlor Swift-Moore-Cottingham House



Summerfield Historic District Summerfield, Dallas County Alabama

Ellen Mertins, 1980 Alabama Historical Commission

Swift-Moore-Cottingham House

#26



Name of Photographer:
Carl V. Kling
Date photograph was taken:
July 1977
Location of negative:

Archives of Alabama Historical
Commission

View:

Exterior, Childers-Tate-Crowe House (16)

photo #27



Ellen Mertins, 1980 Alabama Historical Commission

Baptist Church from NW (3) Photo number 28



Ellen Mertins, 1980 Alabama Historical Commission

House #14, from Marion Road Photo # 29

JAN 2 8 1982



Ellen Mertins, 1980

House # 13, from Marion Road

Photo #30



Ellen Mertins , 1980

House # 15, from Marion Road

Photo # 31



Ellen Mertins, 1980

House #10, from Marion Road

Photo # 32

JAN 2 8 1982



Ellen Mertins, 1980

Campbell- Rush House (#5)

Photograph # 33

JAN 28 1982