

E.W. Marland Mansion Kay Churty Ponca City, Oklahoma




Photo No 3
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: May, 1977

View: From southwest, showing porte cochère at front (west) entrance.



E. W. MARLAND MANSION Photo credit: AASLH

Photo No. 4

side of mansion.

By: Ralph J. Christian, AASLH Negative at: Historic Sites Survey Date: May, 1977 View: From northeast, showing north



E. W. MARLAND MANSION Photo credit: AASLH

Photo No. 5

Negative at: Historic Sites Survey Date: May, 1977

View: Window in formal dining room of mansion.

By: Ralph J. Christian, AASLH



Photo credit: AASLH 901 Monument Road
Ponca City, Oklahoma

Photo No. 6
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey

E. W. Marland Mansion

Date: May, 1977

View: The outer lounge, situated at rear of mansion.



Photo No. 7
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: May, 1977

View: From the east, showing front (east) facade of studio and guest house.