



Darling Inn

SEP 24 1980

Lyndonville, VT

Credit: Christopher W. Closs

Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant / Concord NH

Description: Principal facade of  
Darling Inn showing main block,  
flanking pavilions and entry porti-  
co. Depot Street in foreground is  
the public way bounding the north  
elevation of the structure.

Photograph 1

NOV 24 1980



SEP 24 1980

Darling Inn

Lyndonville, VT

Credit: Christopher W. Closs

Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant / Concord, NH

Description: West elevation front-  
ing on Elm Street showing iron fire  
escape, entry vestibule to former  
taproom/lounge in basement and south  
west wing. Two of three landscape  
shade trees shown.

Photograph 2

NOV 24 1980



Darling Inn  
Lyndonville, VT

SEP 24 1980

Credit: Christopher W. Closs

Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant / Concord, NH

Description: 3/4 view of (l. to r.)  
south and east elevations respective  
ly. Shows kitchen wing, rear serv-  
ice way and roof elevator tower.  
Third landscape shade tree shown at  
extreme right.

Photograph 3

NOV 24 1980



Darling Inn                      **SEP 24 1980**  
Lyndonville, VT  
Credit: Christopher W. Closs  
Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant / Concord, NH  
Description: South elevation show-  
ing "U" shaped plan, kitchen wing  
and porch appendages, concrete  
paved service entrance and rear  
entry portico on southwest wing.  
Photograph 4

NOV 24 1980



Darling Inn  
Lyndonville, VT SEP 24 1980  
Credit: Christopher W. Closs  
Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant 4 Bicentennial  
Square / Concord, NH

Description: 3/4 view shows entry  
vestibule, original lighting fixture  
and doorway to Ladies Parlor at ex-  
treme right.

Photograph 5

NOV 24 1980



Darling Inn  
Lyndonville, VT

SEP 4 1980

Credit: Christopher W. Closs

Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant 4 Bicentennial  
Square / Concord, NH

Description: Main foyer and front  
desk; front office in background.

The elevator is to the right of the  
desk, followed by the grand stair.

Sprinkler system is clearly visible.

Photograph 6

NOV 24 1980



Darling Inn

SEP 24 1980

Lyndonville, VT

Credit: Christopher W. Closs

Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant 4 Bicentennial  
Square / Concord, NH

Description: Main foyer and lounge  
area of lobby in background. Lobby  
fireplace hidden behind row of pan-  
elled piers. Boxed ceiling girts  
and interior architectural details  
also shown.

Photograph 7

NOV 24 1980



Darling Inn  
Lyndonville, VT  
Credit: Christopher W. Closs  
Date: May, 1980  
Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant 4 Bicentennial  
Square / Concord, NH  
Description: View of grand stair  
and hallway to rear exit of main  
block. Panelled piers and boxed  
girts in foreground.  
Photograph 8

**SEP 24 1980**

NOV 24 1980



Darling Inn

SEP 24 1980

Lyndonville, Vt

Credit: Christopher W. Closs

Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant 4 Bicentennial  
Square / Concord, NH

Description: Main lobby area and  
entrance to southwest wing via  
double-leaved doors in background.  
Twin rows of panelled piers and  
boxed ceiling girts seen in fore-  
ground.

Photograph 9

NOV 24 1980



Darling Inn  
Lyndonville, VT

SEP 24 1980

Credit: Christopher W. Closs  
Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant 4 Bicentennial  
Square / Concord, NH

Description: 3/4 view of main lob-  
by and foyer with entry doors to  
Ladies Parlor (background left) and  
hallway to dining room (background  
right).

Photograph 10

NOV 24 1980



Darling Inn

SEP 24 1980

Lyndonville, VT

Credit: Christopher W. Closs

Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant 4 Bicentennial  
Square / Concord, NH

Description: Interior view of  
Ladies Parlor (altered) - 7' wall  
mirror is out of the picture in  
the right foreground.

Photograph 11

NOV 24 1980



Darling Inn  
Lyndonville, VT

SEP 24 1980

Credit: Christopher W. Closs  
Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant 4 Bicentennial  
Square / Concord, NH

Description: 3/4 view of dining  
room interior from doorway of  
Ladies Parlor. Exquisite Federal  
Revival Style fireplace and boxed  
ceiling girts are the focus of the  
background. Open door is mahogany  
with crystal knob.

Photograph 12

NOV 24 1980



Darling Inn  
Lyndonville, VT

SEP 24 1980

Credit: Christopher W. Closs  
Date: May, 1980

Negative filed with Christopher W.  
Closs / Community and Preservation  
Planning Consultant 4 Bicentennial  
Square / Concord, NH

Description: 3/4 view of main  
dining room with doorway and corner  
details visible and sterling silver  
chandeliers. Tile floor is origi-  
nal. Access to kitchen is in left  
background.

Photograph 13

NOV 24 1980