

Hawaii Theatre NOV 1 4 1978 Honolulu, Hawaii Photographs by Tom Hisamura June 1977 Office of Information and Complaint (City and County of Honolulu) Front Elevation at Bethel St./North Elevation at South Pauahi St./Roof (exterior facade elements) Photograph No. 1 MAY 31 1978



NOV 14 1978 Hawaii Theatre Honolulu, Hawaii Photographs by Tom Hisamura June 1977 Office of Information and Complaint (City and County of Honolulu) Front Elevation/Partial South Elevation (exterior facade elements) MAY 31 1978

Photograph No. 2





Honolulu, Hawaii Photographs by Tom Hisamura June 1977 Office of Information and Complaint (City and County of Honolulu)

Hawaii Theatre NOV 14 1978

Front Elevation (exterior facade elements) MAY 31 1978

Photograph No. 3



Hawaii Theatre Honolulu, Hawaii Photographs by Tom Hisamura June 1977 Office of Information and Complaint (City and County of Honolulu) Gallery--Stage/Proscenium Arch

(exterior wall and ceiling elements)

Photograph No.4 MAY 31 1978



Hawaii Theatre NOV 14 1978
Honolulu, Hawaii
Photographs by Tom Hisamura
June 1977
Office of Information and Complaint
(City and County of Honolulu)

Main Auditorium Floor (interior floor, wall and ceiling elements)

Photograph No.5

MAY 31 1970

TOP

Hawaii Theatre

Honolulu, Hawaii

Photographs by Tom Hisamura

June 1977

Office of Information and Complaint

(City and County of Honolulu)

Photograph No. 6

Gallery--Proscenium Box and Columns, and Pipe Chambers above (interior wall elements)

MAY 31 1973



TOP

Hawaii Theatre NOV 1 4 1978
Honolulu, Hawaii
Photographs by Tom Hisamura
June 1977
Office of Information and Complaint
(City and County of Honolulu)

Gallery Wall Panels at the Proscenium Columns (interior wall and elements treatment)

Photograph No. 7 MAY 01 1978



TOP


Hawaii Theatre
Honolulu, Hawaii
Photographs by Tom Hisamura
June 1977

Office of Information and Complaint (City and County of Honolulu)

Gallery--Lionel Walden's Mural

"Glorification of Diana" over the

Proscenium Arch (interior ceiling elements)
Photograph No. 8 MAY 31 1978



Hawaii Theatre Honolulu, Hawaii Photographs by Tom Hisamura June 1977 Office of Information and Complaint (City and County of Honolulu) Mezzanine Stairway--Mid-level Stairway Landing (interior wall elements)

Photograph No. 9 MAY 31 1978

NOV 1 4 1978

Hawaii Theatre
Honolulu, Hawaii
Photographs by Tom Hisamura
June 1977
Office of Information and Complaint

(City and County of Honolulu)

Mezzanine Lobby (interior wall decorations/elements)

NOV-14 1978 Photograph No. 10: MAY 31 1978