## MONTANA HISTORICAL \* ARCHITECTURAL INVENTORY

	Reference #	Date: Summer 1980		
2	Photo # 8 and 9 Direction (N	NE E SE S SW W (NW)		
3 Historic Name: Lower Bridger School CONTACT				
3а	3a Common Name: PHOTO			
4	Address: Bozeman, MT			
5	Program Area: Gallatin County	6 County Code 031 State Code 030		
7		ooundary is right- of way of Bridger Road		
8	C	rintendent of Schools		
9		Street, Bozeman		
10	) Year Built: 1887⊠ Factual ☐ Estimate	ll Location 🔀 Original 🗌 Moved		
12	2 Architect (if known):			
13	Builder/Original Owner (if known)			
14	14 Exterior Materials: ☐ Stone ☐ Brick ☐ Stucco ☒ Wood ☐ Log ☐ Terra-cotta ☐ Concrete			
	☑ Shingle ☐ Other Materials (specify):			
15	15 Condition: ☐ Excellent ⊠Good ☐ Fair ☐ Deteriorated ☐ In Ruins ☐ No Longer Exists			
16	o Retention of Original Design: 🛛 Altered	Major Minor Unaltered		
17	7 Present Use: Community Center	18 Original Use: School		
		eximate dates at which they occurred.		
	with windows on both the east and west on the east wall were relocated on the was added to the north side. The clap wood shingles. The modification to the since they are elements which demonstr	was a simple gable ended, frame structure walls. In the early 1920's the two windows west wall and an enclosed entry vestibull board siding ahs been covered with white e building have not altered its integrity ate the evolution of school house design.		
	with windows on both the east and west on the east wall were relocated on the was added to the north side. The clap wood shingles. The modification to the since they are elements which demonstr	was a simple gable ended, frame structure walls. In the early 1920's the two window west wall and an enclosed entry vestibulle board siding ahs been covered with white e building have not altered its integrity		
20	with windows on both the east and west on the east wall were relocated on the was added to the north side. The clap wood shingles. The modification to th since they are elements which demonstr Located neat the front doot of the ves	was a simple gable ended, frame structure walls. In the early 1920's the two window west wall and an enclosed entry vestibull board siding ahs been covered with white e building have not altered its integrity ate the evolution of school house design.		
20	with windows on both the east and west on the east wall were relocated on the was added to the north side. The clap wood shingles. The modification to th since they are elements which demonstr Located neat the front doot of the ves	was a simple gable ended, frame structure walls. In the early 1920's the two window west wall and an enclosed entry vestibull board siding ahs been covered with white e building have not altered its integrity ate the evolution of school house design. tibule is a hand (cont. in sections 20c essociations Architectural and Engineering		

	20c	Please justify how the location, design, details, materials, and/or workmanship contribute to the property's significance.  operated well pump. To the south of the building are two outdoor privies.  The building is in good condition and is presently used as a community center.		
	20d	Please note if the extant structure/site may demonstrate or yield information about its historic use or construction.		
	21	Neighborhood Context: ☐Unrelated ☐Compatible ☒Integral element ☐Major component of the neighborhood		
continued	21a	If the structure/site contributes to the value of a larger grouping of structures and sites, please describe the visual or historic relationships that the individual structure/site has to that grouping.		
SIGNIFICANCE	22	Environmental/Economic threats to survival: Private Development Zoning Public Works Projects Vanadalism Deterioration Other (specify):		
Ž	23	Recognition in existing historical surveys:		
SS	24	Sources of Documentation: Annaul Trustee Reports 1896-1934		
函	25	Agency Prepared For:		
	26	Name/Address Dave Minor and Paul Bishop		
ÄΗ		Phone # Date:		
PREPARE		Organization: School of Architecture, MSU, Bozeman		
Δ,				
	27	Staff Evaluator: Date: Permission to Nominate X Yes No		
	28	Appears to meet NR Criteria $\boxtimes$ A $\square$ B $\boxtimes$ C $\square$ D $\square$ Does not appear to meet NR Criteria Eligible $\square$ Yes $\square$ No As part of a district $\square$ Yes $\square$ No Individually $\square$ Yes $\square$ No		
	29	UTM References: Zone 12 Easting 505540 Northing 5060850		
E ONLY	30	O Please Return to: State Historic Preservation Office Montana Historical Society 225 N. Roberts St. Helena, Montana 59601		
STAFF USE	31	SHPO Comments:		