



Restoration of the SAN BERNARDINO RANCH

Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

#1 Ranch House Compound. View looking toward north. The Water Storage Tank is at the far left.



Restoration of the SAN BERNARDINO RANCH  
Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

**#2** Ranch House Compound. View looking west.  
From left to right: Main Ranch House, Ice  
House, Water Storage Tank, Wash House, and  
Commissary.



Restoration of the SAN BERNARDINO RANCH

Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

#3 Ranch House Compound. View looking south.  
The Commissary is at the right.





Restoration of the SAN BERNARDINO RANCH  
Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

#4 Main Ranch House. View looking  
northwest.





Restoration of the SAN BERNARDINO RANCH

Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

#5 Main Ranch House. View looking north.  
The Kitchen wing is at the left. The  
commissary is seen in the left background.



Restoration of the SAN BERNARDINO RANCH

Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

#6 Ranch House Compound. View looking north.  
From left to right: Ice House, Wash House,  
Commissary, and Main Ranch House.



Restoration of the SAN BERNARDINO RANCH

Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

#7 Main Ranch House living room.  
View looking northeast.





Restoration of the SAN BERNARDINO RANCH

Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

⑧ Main Ranch House dining room.

View looking northwest.



Restoration of the SAN BERNARDINO RANCH  
Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

⑨ Main Ranch House bedroom(center room  
north side of hallway) showing adobe  
construction.



Restoration of the SAN BERNARDINO RANCH

Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

**#10** Garage. View looking northwest. The Granary is seen at the far right. The Model T Ford is identical to one owned by John Slaughter.





Restoration of the SAN BERNARDINO RANCH  
Main House Compound

04-83-0JB-04 - JB#8302 - GADA#8206

September 22, 1984

GERALD A. DOYLE & ASSOCIATES, P.C.

#11 Granary. View looking north.