




Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Charles H. Ashton  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

View NW towards main house; western  
(original) stone building to left;  
northern (reconstructed) stone  
building to right.  
Photo 1 of 14.



Johnson Hall, ca. 1850

NORTH FRONT OF JOHNSON HALL.

Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Richard W. Hunter  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

---

Circa 1850 view SE of main house prior to late 19th century alterations; western (original) stone building to right; northern (reconstructed) stone building to left (photograph exhibited in west stone building).  
Photo 2 of 14.



Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Richard W. Hunter  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

---

Circa 1900 view N of main house after  
late 19th century alterations; western  
(original) stone building to left  
(photograph exhibited in north stone  
building).

Photo 3 of 14.



Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Richard W. Hunter  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

---

View SE of first floor hallway and  
front door of main house.  
Photo 4 of 14



Johnson Hall

National Historic Landmark

Johnstown, New York

Credit: Richard W. Hunter

Heritage Studies, Inc.

August, 1984. Negative at MARO, NPS.

---

View NW of second floor landing and  
stairway of main house.

Photo 5 of 14.



Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Charles H. Ashton  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

---

View E of main house; western  
(original) stone building to right;  
northern (reconstructed) stone  
building to left; archaeological  
excavations in foreground.  
Photo 6 of 14.



Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Charles H. Ashton  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

---

View N of caretaker's house; garage to  
right.  
Photo 7 of 14.



Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Richard W. Hunter  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

---

View SE along West State Street  
showing western edge of landmark to  
left of road.  
Photo 8 of 14.



Johnson Hall

National Historic Landmark

Johnstown, New York

Credit: Richard W. Hunter

Heritage Studies, Inc.

August, 1984. Negative at MARO, NPS.

---

View NW along West State Street (to left) and Hall Avenue (to right) showing southern tip of landmark and statue of Sir William Johnson.  
Photo 9 of 14.



Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Richard W. Hunter  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

View NW of statue of Sir William  
Johnson at southern tip of landmark.  
Photo 10 of 14.



Johnson Hall

National Historic Landmark

Johnstown, New York

Credit: Charles H. Ashton

Heritage Studies, Inc.

August, 1984. Negative at MARO, NPS.

---

View N along Hall Avenue showing eastern edge of landmark to left of road; main house and northern (reconstructed) stone building visible at end of road to left.

Photo 11 of 14.



Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Richard W. Hunter  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

---

View W of mill dam remains in Hall  
Creek.  
Photo 12 of 14.



Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Richard W. Hunter  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

---

View SE (downstream) of remains of  
mill site on Hall Creek.  
Photo 13 of 14.



Johnson Hall  
National Historic Landmark  
Johnstown, New York  
Credit: Richard W. Hunter  
Heritage Studies, Inc.  
August, 1984. Negative at MARO, NPS.

---

View N of remains of mill site on Hall  
Creek.  
Photo 14 of 14.