




1. William Scarborough House
2. Chatham Co., Georgia
3. Ms. Sherry Johnson
4. August 1997
5. Negative - NPS, SERO
6. Front view - looking  
west -  
~~east~~ - of the Scarborough  
House
7. Photograph I



1. William Scarbrough House
2. Chatham Co., Georgia
3. Ms. Sherry Johnson
4. August 1997
5. Negative - NPS, SERO
6. View of brick wall associated with the Scarbrough House in the rear of the building, looking ~~to~~ north into garden area. Note NHH plaque on wall.
7. Photograph 2



Enter through  
this door

1. William Scarborough House
2. Chatham Co., Georgia
3. Ms. Sherry Johnson
4. August 1997
5. Negative - NPS, SERO
6. View of front of Scarborough House showing details - <sup>view is from my</sup> ~~front~~ the north facing south.
7. Photograph 3





1. William Scarborough House
2. Chatham Co., Georgia
3. Photographer -  
unknown
4. Date unknown
5. Negative - Slips of  
the Sea Museum
6. View of south  
portico with cast-iron  
railing & columns
7. Photograph 4





14-127

Helen B.

1. William Scarborough House
2. Chatham Co., Georgia
3. James Vernon McDonough-  
photographer
4. ca. 1949
5. Negative - Ships of the  
Sea Museum
6. South portico  
with cast-iron  
railing & columns
7. Photograph 5



Scarborough House

1. William ~~Smith~~

2. Chatham Co., Georgia

3. Ms. Sherry Johnson

4. August 1997

5. Negative - NPS, SERO

6. Interior view of  
central hall

7. Photograph 6




1. William Scarborough House
2. Chatham Co., Georgia
3. Ms. Sherry Johnson
4. August 1997
5. Negative - NPS, SERO
6. Interior view of  
second floor gallery  
above the central  
hall.
7. Photograph 7





1. William Scarborough House
2. Chatham Co., Georgia
3. Photographer unknown
4. ca. 1955
5. Negative - Ships of the Sea Museum, Savannah
6. View of rear facade showing gallery constructed off the ballroom.
7. Photograph 8



1. Willicam Scarborough House
2. Chatham Co., Georgia
3. Photographer unk.
4. ca. 1910s
5. Negative - Slips of  
the Sea Museum
6. View of east & south  
facades and water  
gate
7. Photograph 9



1. William Scarborough House
2. Chat ham Co., Georgia
3. Photographer unknown
4. ~~1930's~~ 1940's
5. Negative - Ships of the Sea Museum, Savannah
6. View of south & east facades. Note watergate gone
7. Photograph 10



1. William Scarborough House
2. Chatham Co., Georgia
3. ~~ca~~ Photographer unknown
4. c. 1955
5. Negative - Slips of the Sea Museum, Savannah
6. View of west and north facades with northside service porch & breezeways installed by school.
7. Photograph 11





1. William Scarborough House
2. Chatham Co., Georgia
3. Ms. Sherry Johnson
4. August 1997
5. Negatives - NPS, SERO
6. Front Facade of building ~~at~~ after 1996-97 Rehabilitation
7. Photograph 12



1. William Scarborough House

2. Chatham Co., Georgia

3. Ms. Sherry Johnson

4. August 1997

5. Negatives - NPS, SERO

6. View of reconstructed  
water gate after  
1996-97 Rehabilitation

7. Photograph 13



1. William Scarborough House
2. Chatham Co., Georgia
3. Sherry Johnson
4. August 1997
5. Negative - NPS, SERO
6. New wall built to separate building from parking lot. 1996-97 Rehab.
7. Photograph 14





1. William Scarborough House
2. Chatham Co., Georgia
3. Sherry Johnson
4. August 1997
5. Negative - NPS, SERO
6. New Rear gallery  
entrance - part of  
1996-97 Rehabilitation
7. Photograph 15