




**RANKIN, JOHN, HOUSE**  
**Ripley, Ohio**  
**North elevation, long-range view**  
**Photo: Scott Roth, 1996**



**RANKIN, JOHN, HOUSE**  
**Ripley, Ohio**  
**North (rear) elevation**  
**Photo: Scott Roth, 1996**



**RANKIN, JOHN, HOUSE**  
**Ripley, Ohio**  
**East elevation**  
**Photo: Scott Roth, 1996**



**RANKIN, JOHN, HOUSE**  
Ripley, Ohio  
South and west elevations  
Photo: Scott Roth, 1996



**RANKIN, JOHN, HOUSE**

**Ripley, Ohio**

**Main (south) elevation from Liberty  
Stairway**

**Photo: Scott Roth, 1996**



**RANKIN, JOHN, HOUSE**  
Ripley, Ohio  
Liberty Stairway, from Rankin  
House toward Ohio River  
Photo: Scott Roth, 1996



**RANKIN, JOHN, HOUSE**  
**Ripley, Ohio**  
**Stairway and first floor hall from**  
**rear entrance**  
**Photo: Scott Roth, 1996**



**RANKIN, JOHN, HOUSE**  
Ripley, Ohio  
First floor, southwest room (parlor)  
Photo: Scott Roth, 1996





**RANKIN, JOHN, HOUSE**  
Ripley, Ohio  
Mantle, first floor southeast room  
Photo: Scott Roth, 1996