



Reynolds Homestead  
Rock Spring Plantation  
On Va. 798, 1 mi. north  
of Critz, via Va. 626  
Critz, Virginia

Photo by: Ralph J. Christian, AASLH  
Negative at: Historic Sites Survey  
November 1976

Photo No. 1  
View: Front (north) facade and  
detached kitchen.



REYNOLDS HOMESTEAD

Photo credit: AASLH

Reynolds Homestead  
Rock Spring Plantation

On Va. 798, 1 mi. north  
of Critz via Va. 626

Critz, Virginia

Photo by: Ralph J. Christian, AASLH

Negative at: Historic Sites Survey

November 1976

Photo No. 2

View: Portions of ice house and milk  
house, rear of kitchen, and  
portion of rear (south) facade  
of house.



REYNOLDS HOMESTEAD

Photo credit: AASLH

Reynolds Homestead  
Rock Spring Plantation  
On Va. 798, 1 mi. north  
of Critz via Va. 626  
Critz, Virginia

Photo by: Ralph J. Christian, AASLH  
Negative at: Historic Sites Survey  
November 1976

Photo No. 3  
View: East side of Reynolds bedroom  
with Chinese Chippendale  
Stairway leading to upper story



REYNOLDS HOMESTEAD

Photo credit: AASLH



Reynolds Homestead  
Rock Spring Plantation  
On Va. 798, 1 mi. north  
of Critz via 626  
Critz, Virginia

Photo by: Ralph J. Christian, AASLH  
Negative at: Historic Sites Survey  
November 1976

Photo No. 4  
View: West wall of Reynolds bedroom  
showing fireplace and  
furnishings.