



Photo #1
Harmony Mills
Cohoes, Albany County, New York
East facade of Mill No. 1, and a portion of
the 1837 Mill
Photo: Ann L. May, September 1994



Photo #2

Harmony Mills

Cohoes, Albany County, New York

West facade of Mill No. 3, Central Pavilion

Photo: Ann Luby, September 1994




Photo #3

Harmony Mills

Cohoes, Albany County, New York
Office Building and Mill No. 3, intersection
of Vliet St. and North Mohawk St.

Photo: Christopher Quick, July 1998



Photo #4
Harmony Mills
Cohoes, Albany County, New York
Interior of Mill No. 3, looking north on top
floor
Photo:Christopher Quick, July 1998



Photo #5
Harmony Mills
Cohoes, Albany County, New York
Interior of Mill No. 3, detail of belt power
system
Photo: Christopher Quick, July 1998




Photo #6
Harmony Mills
Cohoes, Albany County, New York
Office Building and Boiler House
Photo: Christopher Quick, July 1998




Photo #7
Harmony Mills
Cohoes, Albany County, New York
Picker House, Storerooms, and Pump
House, N. Mohawk St.
Photo: Christopher Quick, July 1998




Photo #8

Harmony Mills

Cohoes, Albany County, New York
Company Housing, School St. and N.
Mohawk St.

Photo: Christopher Quick, July 1998



Photo #9
Harmony Mills
Cohoes, Albany County, New York
Tenements on North Mohawk St.
Photo: Ann Luby, September 1994



Photo #10
Harmony Mills
Cohoes, Albany County, New York
Tenements on east side of Cataract St.
Photo: Ann Luby, September 1994




Photo #11
Harmony Mills
Cohoes, Albany County, New York
Gate House
Photo: Christopher Quick, July 1998




Photo #12
Harmony Mills
Cohoes, Albany County, New York
Cohoes Company Dam
Photo: Christopher Quick July 1998




Photo #13
Harmony Mills
Cohoes, Albany County, New York
Power Canal bridge
Photo: Christopher Quick, July 1998



Harmony Mills Historic District
Cohoes, New York

3



Harmony Mills Historic
District

Cohoes, New York

9



Harmony Hill Historic
District
Cathars, New York
8



Harmony Mills Historic District

Caboose, New York

5



This is one of two original
turbines, circa 1871-1873,
housed inside part of the
Harmony Mills complex in
Cohoes