



Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 1

By: Ralph J. Christian, AASLH

Negative at: Historic Sites Survey

Date: November, 1977

View: From southwest, showing front
(west) facade and south end.



Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 2

By: Ralph J. Christian, AASLH

Negative at: Historic Sites Survey

Date: November, 1977

View: From northwest, showing front
(west) facade and portion of
north end.



Toledo Society for the Handicapped

Toledo Society for the Handicapped

Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 3

By: Ralph J. Christian, AASLH

Negative at: Historic Sites Survey

Date: November, 1977

View: From east, showing rear (east)
facade.



Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 4

By: Ralph J. Christian, AASLH

Negative at: Historic Sites Survey

Date: November, 1977

View: From northeast, showing portion
of rear (east) facade and north side.



Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 5

By: Ralph J. Christian, AASLH

Negative at: Historic Sites Survey

Date: November, 1977

View: Interior, showing stairway on
first floor.