Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 1
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: November, 1977

View: From southwest, showing front (west) facade and south end.

Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 2
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: November, 1977

View: From northwest, showing front (west) facade and portion of north end.

Toledo
Society
for the
Handicapped
Toledo
Society
for the
Handicapped

Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 3
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: November, 1977

View: From east, showing rear (east) facade.

Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 4
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: November, 1977

View: From northeast, showing portion of rear (east) facade and north side.

Edward D. Libbey House
2008 Scottwood Avenue
Toledo, Ohio

Photo No. 5
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: November, 1977

View: Interior, showing stairway on first floor.