



3/20 View east along 1500 block of Hollins

Street with Mencken House the fifth house from the left




19/20 View northwest of garden from house



18/20 View north, garden from house

1/20 Facade or south elevation of house






20/20 View of north wall in garden

2/20 Facade entranceway



PROPERTY OF  
J. L. MEXLEY  
A PARTNER IN THE  
FIRM OF MEXLEY & COMPANY



13/20 Interior, first floor, view of south-east corner of kitchen, transomed door is original back entrance into garden



14/20 Interior, second floor, northwest corner of front room which Mencken used as a study






15/20 Interior, Third floor, view of north-  
corner of front room



16/20 Interior, third floor, view of kitchen installed in el of front room, doorway leads into stair hall, partition on left was added when the kitchen was installed

17/20 View of north or rear elevation of house





4/20 View of 1500 block of Hollins Street from Union Square with Mencken House in center of photograph

5/20 Interior, first floor, view of vestibule  
paneling and entrance doors



6/20 Interior, first floor, view of stairhall  
from vestibule, door at end of hall leads  
into back parlor



7/20 Interior first floor, view of stair hall  
and vestibule toward Union Square, plaque  
on vestibule door is inscribed with the  
name of Mencken's father



8/20 Interior, first floor, view of front parlor with hall and vestibule visible through arched doorway





9/20 Interior, first floor, view from back  
parlor into front parlor



10/20 Interior, first floor fireplace on west wall of back parlor



11/20 Interior, first floor, view of northeast corner of back parlor





12/20 Interior, first floor, view of north wall of dining room