



SANTANONI PRESERVE


Essex County, New York

Gate Lodge

Photo by Austin O'Brien, 1994



SANTANONI PRESERVE
Essex County, New York
Barn at Farm Complex
Photo by Austin O'Brien, 1994



SANTANONI PRESERVE

Essex County, New York

Farm Complex with Creamery at middle right

Photo by Austin O'Brien, 1994



SANTANONI PRESERVE

Essex County, New York

Gardener's Cottage at Farm Complex

Photo by Austin O'Brien, 1994



SANTANONI PRESERVE
Essex County, New York
Carriage Drive and South Culvert looking north
Photo by Austin O'Brien, 1994







SANTANONI PRESERVE

Essex County, New York

Main Camp, northwest elevation of center pavilion

Photo by Austin O'Brien, 1994

DANGER
KEEP OUT





SANTANONI PRESERVE

Essex County, New York

Main Camp, east-center pavilion with east pavilion beyond

Photo by Austin O'Brien, 1994



SANTANONI PRESERVE
Essex County, New York
Lake-facing veranda, looking west
Photo by Austin O'Brien, 1994



SANTANONI PRESERVE

Essex County, New York

Main Camp, southeast elevation, center pavilion with kitchen on left

Photo by Austin O'Brien, 1994



SANTANONI PRESERVE
Essex County, New York
Kitchen, rear elevation
Photo by Austin O'Brien, 1994