

BUILDING NO. 29, Sitka, Alaska Photog. unknown ca. 1883 Fred Fickett Coll., University of Alaska-Anchorage Archives Building 29 before addition, original gallery

PHOTO-1

roof: vw. NE



BUILDING NO. 29, Sitka, Alaska
Photog. unknown
Ca. 1887
Copper River-Kennicott Coll., Alaska
Historical Library
Building No. 29, showing new addition; NE
PHOTO-2

PHOTO CREDIT REQUIRED:

Alaska Historical Library



William Partridge, Photog. 1887

Anchorage Museum of History and Art

after addition; East

Lincoln Street, showing front of Bldg. 29



#### BUILDING NO. 29, Sitka, Alaska Photq. unknown Ca. 1890 Copper River-Kennicott Coll., Alaska Historical Library Building No. 29 after addition; SW



# BUILDING NO. 29, Sitka, Alaska Photog. unknown Before 1894 Anghorage Muscum of History and Art

PHOTO-5

Before 1894
Anchorage Museum of History and Art
Lincoln Street, showing front of Bldg. 29

with new porch; SW



#### BUILDING NO. 29, Sitka, Alaska Paul J. F. Schumacher, Photog. Sitka National Historical Park 1959

Building No. 29; SE

PHOTO=6



#### BUILDING NO. 29, Sitka, Alaska Paul J. F. Schumacher, Photog. 1959 Sitka National Historical Park

Building No. 29; SW



#### BUILDING NO. 29, Sitka, Alaska Charles W. Snell, Photog. 1961

Sitka National Historical Park Building 29 with exterior modifications

PHOTO = 8



#### BUILDING NO. 29, Sitka, Alaska David Snow, Photog.

1985 NPS-Alaska Regional Office Building 29 before 1985 renovations



David Snow, Photog. 1985

PHOTO-10

NPS-Alaska Regional Office

Rotting logs in east wall; NE



#### BUILDING NO. 29, Sitka, Alaska David Snow, Photog. 1985 NPS-Alaska Regional Office

Close up view, rotting logs in east wall; W



David Snow, Photog. 1985 NPS-Alaska Regional Office

Interior view during renovations; 1st floor toward NE corner



David Snow, Photog. 1985 NPS-Alaska Regional Office Interior view during renovations; 1st floor toward rear wall and partition (SW) PHOTO-13



#### BUILDING NO. 29, Sitka, Alaska Kate Lidfors, Photog.

Kate Lidfors, Photog. 1985 NPS-Alaska Regional Office Wallpaper removed from first floor walls



BUILDING NO. 29, Sitka, Alaska Kate Lidfors, Photog. 1985 NPS-Alaska Regional Office Original partition wall opened for traffic flow PHOTO-15



#### BUILDING NO. 29, Sitka, Alaska Kate Lidfors, Photog.

1985 NPS-Alaska Regional Office Original interior log wall showing hewer's incisings



#### BUILDING NO. 29, Sitka, Alaska Kate Lidfors, Photog. 1985 NPS-Alaska Regional Office Original interior log wall left exposed after renovation



#### BUILDING NO. 29, Sitka, Alaska Kate Lidfors, Photog. 1985

Front exterior view after renovations; SW

PHOTO-18

NPS-Alaska Regional Office



## BUILDING NO. 29, Sitka, Alaska Kate Lidfors, Photog.

PHOTO-19

1985

NPS-Alaska Regional Office Front exterior view after renovations; SE



## BUILDING NO. 29, Sitka, Alaska Kate Lidfors, Photog. 1985

NPS-Alaska Regional Office Rear exterior view; original portion on right

PHOTO-20



## BUILDING NO. 29, Sitka, Alaska Photog. unknown ca. 1890

Sheldon Jackson College Archives

Thomas and Tomina Tilson



BUILDING NO. 29, Sitka, Alaska Photog. unknown ca. 1910 Lena Tilson Freeland, private collection

Family gathering, interior Building 29



## BUILDING NO. 29, Sitka, Alaska Photog. unknown Ca. 1960 Sitka National Historical Park

Aerial view of Sitka and Lincoln St., SE




BUILDING NO. 29, Sitka, Alaska Photog. unknown Date unknown

Sheldon Jackson College Archives View of Sitka and Lincoln Street, east



BUILDING NO. 29, Sitka, Alaska Photog. unknown Date unknown Sheldon Jackson College Archives View of Sitka, showing back of Bldg. 29, NW



BUILDING NO. 29, Sitka, Alaska Photog. Unknown Ca. 1890

Alaska Historical Library View of Lincoln Street, East



BUILDING NO. 29, Sitka, Alaska Photog. Unknown Ca. 1900

Sheldon Jackson College Archives

Lincoln Street, view west