

1. Socialist Labor Party Hall 46 Granite Street 2. Barre, VT Washington County 3. Photographer! Robin Backin 4. Date of photograph: 8/10/95 5. Location of negative: Newberry Library 60 w. Walton St. 6. Front & south side of building, facing north east





August 1995





Socialist Labor Party Hall - Exterior side view.



Socialist Labor Party Hall - Upstairs front room showing: temporary supports for roof timbers, damaged ceiling and wall plaster, missing wainscoting, and deteriorated paint.



Socialist Labor Party Hall - Main meeting room after partial restoration. Work to be completed includes restoration of stage and wings at far end, replacement of bricked in window at back and sides, and repainting in original finishes of blue, red and gold and stenciling.