



Goodrich, Solomon Homestead
Georgia, Franklin County, Vermont

Sarah Hadd 5/03.

Negative Filed at VT Division for Historic Preservation.

South + East Facade of Non-contributing Outbuilding,

Building #4, and Contributing Outbuilding, Building #3;

East facade of Summer Kitchen, Building #2; South

Facade of Main Block, Building #1, in Background

Photograph #1 - Context



Goodrich, Solomon Homestead

Georgia, Franklin County, Vermont

Sarah Hudd 5/03

Negative Filed at VT Division for Historic Preservation.

East Facade Main Block, Building #1

Photograph #2 - 3/4 View Main Facade



Goodrich, Solomon Homestead

Georgia, Franklin County, Vermont

Sarah Hadd 5/03

Negative Filed at VT Division for Historic Preservation.

North + South Facades of Main Block, Building #1, and

North Facade of Summer Kitchen, Building #2.

Photograph #3 - $\frac{3}{4}$ View Rear + Side Facades

VI- 1-11-11 155811 16 20 >



4181

Goodrich, Solomon Homestead
Georgia, Franklin County, Vermont

Sarah Hadd 5/03

Negative Filed at VT Division for Historic Preservation.

East Facade Main Block, Building #1.

Photograph #4 - Significant Exterior Detail



Goodrich, Solomon Homestead
Georgia, Franklin County, Vermont

Sarah Hadd 5/03

Negative Filed at VT Division for Historic Preservation.

Interior of Main Block, Building #1, Kitchen Looking into
Living Room.

Photograph # 5-Interior View.

194 5-11-11 2000 10 11



Goodrich, Solomon Homestead
Georgia, Franklin County, Vermont

Sarah Hadd 5/03

Negative Filed at VT Division for Historic Preservation.

East + South Facades of Summer Kitchen, Building #2,
and Contributing Outbuilding, Building #3.

Photograph #6 - Related Buildings

57-1-11-11 1883-1884 80 X