

Rick Wilson MAY 23 1977 March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 1. Photo taken from the southwest showing the facade of the church.

NOV 17 1977



Rick Wilson MAY 2 3 1977 March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 2. Photo taken from the south showing the detail of the front entrance.

NOV 17 1977

PROPERTY OF THE NATIONAL REGISTER




Rick Wilson
March 1977
MAY 23 1977
Kentucky Heritage Commission
Frankfort, Kentucky

Photo 3. Photo taken from the northeast.

NOV 17 1977

PROPERTY OF THE NATIONAL REGISTER



Rick Wilson MAY 23 1977
March 1977
Kentucky Heritage Commission
Frankfort, Kentucky

Photo 4. Photo taken from the south showing the detail of the dovetail notching.

NOV 17 1977



Rick Wilson March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 5.0 Photo taken from the south showing the pinned eave log.

NOV 17 1977

PROPERTY OF THE NATIONAL REGISTER



Rick Wilson March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 6. Interior photo showing the early church benches.

MAY 23 1977

NOV 17 1977

