

AUG 3 1978

## рното #1 **8<sup>3</sup>**

HOTEL LA ROSE, SANTA ROSA, CALIF.

VIEW Somma County

North west face of the building North faces fifth street west faces Wilson Street Photographer is facing southeast

## Photographer and holder of negatives DAN PETERSON, AIA, ARCHITECT May 1977

JAN 24 1978



PHOTO # 2 3 AUG 3 1978 HOTEL LA ROSE, SANTA ROSA, CALIF. VIEW Series The view of the building (northwest faces) related to its environment. view taken from railroad tracks looking east across the park. the trees are seen in a 1922 photograph.

## PHOTOGRAPHER AND HOLDER OF NEGATIVES DAN PETERSON, AIA, ARCHITECT MAY 1977

JAN 24 1978



PHOTO #3 **3** AUG 3 1978 HOTEL LA ROSE, SANTA ROSA, CALIF. VIEW **Servers** Southwest faces showing the plastered stone on the wall which adjoins the adjazent property. Photographer is looking North.

## PHOTOGRAPHER AND HOLDER OF NEGATIVES DAN PETERSON, AIA, ARCHITECT

MAY 1977 JAN 241978