

Name: The Site of the J.H. Wilkerson and Son Brickworks

Location: Milford, Delaware

Photographer: George Rineer Date: 1976 Location of Negative: HAER, Washington, D.C. Kent Conty

Description: South side of Main shed which houses brick machine


Photograph Number: K-360 (1) NOV 29 1977



Name: The site of the J.H. Wilkerson and Son Brickworks Location: Milford, Delaware Kent Could Photographer: George Rineer Date: 1976 Location of Negative: HAER, Washington, D.C.

Description: Northwest corner of main shed which houses brick machine

Photograph Number: K-360 (2) NOV 59 1977



Name: The site of the J.H. Wilkerson and Son Brickworks

KEN County


29

Location: Milford, Delaware

Photographer: George Rineer Date: 1976 Location of Negative: HAER, Washington, D.C.

Cescription: Machinery of disintegrator process

Photograph Number: K-360 (3) NOV 291977



The site of the J.H. Wilkerson and Son Brickworks Name:


399

Location: Milford, Delaware

KENT County Photographer: George Rineer Date: 1976 HAER, Washington, D.C. Location of Negative:

Description: Pug Mill

NOV 29 1977 K-360 (4) Photograph Number: JUL 1 2 1978



Name: The site of the J.H. Wilkerson and Son Brickworks

Location: Milford, Delaware

Photographer: George Rineer Date: 1976 Location of Negative: HAER, Washington, D.C.

Description: Pug mill above and brick machine below

Photograph Number:

K-360 (5)

NOV 29 1977

KENT COUNTY


499

JUL 12 1978



The site of the J.H. Wilkerson and Son Brickworks inmed Kent County Locationa Milford, Delaware Photographers George Rineer 529 1976 Local box of Negatives HAER, Washington, D.C. Discutter in foreground K-360 (6) NOV 291977 .111 1 2 1978

and an and the second sec



The site of the J.H. Wilkerson and Son Brickworks Namasi 689 KENT COUNTY Location: Milford, Delaware Photographer: George Rineer - Date: 1976 Location of Negative: HAER, Washington, D.C. Description: Brick drying pallet set on a metal cart for transport to the brick drving shed. Photograph Numbers K-360 (7) NOV 291977



Name: The site of the J.H. Wilkerson and Son Brickworks Location: Milford, Delaware 789 Photographer: George Rineer 789 Date: 1975 Location of Negative: HAER, Washington, D.C.

Description:

brick kiln (south side)

Photograph Number: K-360 (8) NOV 2.9 1977



Name: The site of the J.H. Wilkerson and Son Brickworks

9 of 1 KENT courty

Location: Milford, Delaware

Photographer: George Rineer Date: 1975 Location of Negative: HAER, Washington, D.C.

Description: Interior of brick kiln

Photograph Number: K-360 (9) NOV 2 9 1977