

Don Shively, Public Information April 1976 Kentucky Heritage Commission Frankfort, Kentucky

Photo $1\mathcal{D}^{\mathcal{B}}$ View of front of house (southwest elevation).

JAN 2 0 1978

JUL 14 1977



Don Shively, Public Information April 1976 Kentucky Heritage Commission Frankfort, Kentucky

Photo 2. ⁸/₈ Front facade showing detail of Victorian hoods over windows and entrance with transom in recessed panelled frames.



Don Shively, Public Information April 1976 Kentucky Heritage Commission Frankfort, Kentucky

Photo 3. PRear of house showing ell adjoining northeast end.

JAN 20 1978 JUL 1 4 1977



Don Shively, Public Information April 1976 Kentucky Heritage Commission Frankfort, Kentucky

Photo $4.9^{\%}$ View of east side of house and more recently enclosed porch attached to rear stone ell. JAN 2 0 1978 JUL 1 4 1977



Don Shively, Public Information April 1976 Kentucky Heritage Commission Frankfort, Kentucky

Photo 5. North view of Wiles property to the rear of main house. Note stone icehouse at center. JUL 1 4 1977



Lexington Herald-Leader July 1976

JUL 14 1977

JAN 2 0 1978

Photo 6^{BC} Central hall facing southwest toward front entrance.



Lexington Herald-Leader July 1976

Photo #7 8 8 East parlor. JUL 14 1977

JAN 2 0 1978



Lexington Herald-Leader July 1976

JUL 14 1977

Photo #8 \$ 8 Ell section, facing north.

JAN 2 0 1978

