

Public Information Photographer Department of Public Information Frankfort, KY June 1976

Photo 1. Georgetown Post Office, view from southeast.



Public Information Photographer
Department of Public Information
Frankfort, KY
June 1976

Photo 2.3 North side of Main Street facing east. Presbyterian Church on far left; church annex to the right. JAN 161978



Gloria Mills
Kentucky Heritage Commission
Frankfort, KY
October 1975

Photo 3. Looking east, Emison House at far left; Eastham House is beyond the arched entrance.



Gloria Mills
Kentucky Heritage Commission
Frankfort, KY
October 1975

Photo 4. Looking east; Mahoney House in center; Green House at far right. JAN 161978



Public Information Photographer
Department of Public Information
Frankfort, KY
June 1976

Photo 5. Shropshire House, No. 8, viewed from southwest.



Public Information Photographer Department of Public Information Frankfort, KY June 1976

Photo 6.9 The Offutt House, No. 9, viewed from southwest.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Photo 7. Oldham House, No. 10, viewed from southeast. Offutt House to the left 16 1978



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

JUN 7 1978

Photo 8. South facade of the Heizer House, No. 11.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Photo 9. The Drake House, No. 12, viewed from southeast.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Photo 10. Smith House, No. 13, viewed from southwest.



Ann Bevins Route 4, Lexington Pike Georgetown, KY 1973

446

Photo ll. South facade of John B. Graves House, No. 14.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Photo 12. View of the Shuff House, No. 15, from southeast.



Gloria Mills
Kentucky Heritage Commission
Frankfort, Kentucky
October 1975

JUN 7 1978

Photo 13. View from southeast. Grover House at right.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

JUN 7 197

Photo 14. South facade of Smetanko House.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973
JUN 7 1978

Photo 15. May House, No. 18, viewed from southeast.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

745 JUN 7 1978

Photo 16. Watson House, No. 19, viewed from southeast.



Ann Bevins Route 4, Lexington Pike Georgetown, Kentucky 1973

Photo 17. Bryan House, No. 20, south facade.



Ann Bevins Route 4, Lexington Pike Georgetown, Kentucky 1973

Photo 18. Gatewood House, No. 21, viewed from southeast.



Public Information Photographer Department of Public Information Frankfort, KY June 1976

0746

Photo 19. South facade of H. C. Blackburn House, No. 22.



Gloria Mills
Kentucky Heritage Commission
Frankfort, Kentucky
October 1975
JUN 7 1978

Photo 20. William H. Moody House, No. 23, viewed from southwest.



Gloria Mills
Kentucky Heritage Commission
Frankfort, Kentucky
October 1975
JUN 7 1978

Photo 21. South facade of Michael Goddard House, No. 24.

JAN 1 6 1978



Gloria Mills Kentucky Heritage Commission Frankfort, Kentucky October 1975

Jun / 1978

Photo 22. South facade of Philemon E. Mitchell House, No. 25.



Public Information Photographer
Department of Public Information
Frankfort, KY
June 1976

Photo 23. Scott County Public Library, No. 26, viewed from northeast. JAN 161978



Public Information Photographer
Department of Public Information
Frankfort, KY
June 1976
JUN 7 1978

Photo 24. Owens House, No. 27, viewed from northwest.



Public Information Photographer
Department of Public Information
Frankfort, KY
June 1976

JUN 7 1978

Photo . John Elliott House, No. 28, in center of house. Owens House to the right. View from northwest. JAN 161978



Public Information Photographer Department of Public Information Frankfort, KY June 1976

Photo 26 East side of the McKnight Apartment Building, No. 24. JAN 161978



Public Information Photographer Department of Public Information Frankfort, KY June 1976

Photo 27. The Allegaire House, No. 30, viewed from northeast. Original section is on the right.

JAN 1 6 1978



Public Information Photographer
Department of Public Information
Frankfort, KY
June 1976

JUN 7 1978

Photo 28. North facade of the Tarleton House, No. 31.




Public Information Photographer
Department of Public Information
Frankfort, KY
June 1976

JUN 7 1978


Photo 29. Gragg House, No. 32, viewed from northeast.

JAN 161978



Gloria Mills
Kentucky Heritage Commission
Frankfort, KY
October 1975

Photo 30. View of James W. Grant House, No. 33, taken from the east.



Gloria Mills Kentucky Heritage Commission Frankfort, KY October 1975

Photo 31. East and north (front) sides of Rankin House, No. 34, looking southwest.



Public Information Photographer Department of Public Information Frankfort, KY June 1976

46

Photo 32. Rankin House slave quarters in rear of residence.



Gloria Mills Kentucky Heritage Commission Frankfort, KY October 1975


Photo 33. Looking east with Harvey C. Graves House, No. 35, at the left, Rankin House, No. 34, at right.



Gloria Mills Kentucky Heritage Commission Frankfort, KY October 1975

46

Photo 34. South facade of Dr. John A. Lewis House, No. 36.



Gloria Mills Kentucky Heritage Commission Frankfort, KY October 1975

0 46

Photo 35. North facade of the Laura Rankin House, No. 37.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Photo 36. North facade of the G. H. Nunnelly House, No. 38.



Ann Bevins Route 4, Lexington Pike Georgetown, Kentucky 1973

Photo 37. View of the Oscar Carrick House from southeast.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Photo 38. The Ward House, No. 40, viewed from southeast.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Photo 39. South facade of the Betty Ware House, No. 41.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Photo 40. James F. Beatty House, northeast view.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Photo 41. St. John's Roman Catholic Church, No. 43, viewed from northwest.



Ann Bevins
Route 4, Lexington Pike
Georgetown, Kentucky
1973

Dué

Photo South facade of the James W. Grant House, No. 33.

JAN 161978



Gloria Mills Kentucky Heritage Commission Frankfort, KY October 1975 JAN 161978

Photo 43. Looking east down south side of Main Street. Building No. 46 is at far left, No. 45 is in center, St. John's Catholic Church at far right.



Gloria Mills Kentucky Heritage Commission Frankfort, KY October 1975

246

Photo 44. The Will Rankin, No. 46, viewed from the northwest. JAN 1 6 1978



Public Information Photographer Department of Public Information Frankfort, KY June 1976

Photo 45. The Steffee-Spears, No. 47, House viewed from the northeast.



Public Information Photographer Department of Public Information Frankfort, KY June 1976

Photo 42. Rectory of St. John's, No. 44, viewed from northeast.