



Name: The Captain Ebe Chandler House

Location: Corner of Main and Reed Sts. \* Frankford, DE

Photographer: Dick Carter

Date: Sept. 1978

Location of Negative: Hall of Records, Dover, DE.

Description: View of northwest end and front of house.

Photograph Number: One of seven

AUG 2

1979

SEP 20 1979



Name: The Captain Ebe Chandler House

Location: Corner of Main and Reed Sts., Frankford, DE

Photographer: Dick Carter

Date: Sept. 1978

*Sussex County*


Location of Negative: Hall of Records, Dover, DE

Description: View of southeast end of house and rear.

Photograph Number: Number two of seven

AUG 2 1979

SEP 20 1979



Name: The Captain Ebe Chandler House

Location: Corner of Main and Reed Sts., Frankford, DE

Photographer: Dick Carter

Date: Sept. 1978

*Sussex County*

Location of Negative: Hall of Records, Dover, DE

Description: Detail of front of house showing entry  
and left front cross gable.

Photograph Number: Number three of seven.

SEP 20 1979

AUG 2 1979



Name: The Captain Ebe Chandler House

Location: Corner of Main and Reed Sts., Frankford, DE

Photographer: Dick Carter

Date: Sept., 1978

Location of Negative: Hall of Records, Dover, DE

*Sussex County*

Description: Detail of gazebo at southeast corner of porch.

Photograph Number: Number four of seven

SEP 20 1979

AUG 2 1979





Name: The Captain Ebe Chandler House

Location: Corner of Main and Reed Streets, Frankford, DE

Photographer: Dick Carter

Date: Sept. 1978

Location of Negative: Hall of Records, Dover, DE

*Sussex County*

Description: View of three remaining out-buildings at rear of house. They are, left to right, wood shed, privy, and small shed housing furnace.

Photograph Number: Number five of seven.

SEP 20 1979

AUG 2 1979



Name: Captain Ebe Chandler House

Location: Corner of Main and Reed Sts., Frankford, DE

Photographer: Dick Carter

Date: Sept., 1978

Location of Negative: Hall of Records, Dover, DE


*Susser Co.*

Description: View of front parlor and doorway leading to dining room.

Photograph Number: Number six of 7

SEP 20 1979

AUG 2 1979



Name: The Captain Ebe Chandler House

Location: Corner of Main and Reed Sts., Frankford, DE

Photographer: Dick Carter

Date: Sept., 1978

Location of Negative: Hall of Records, Dover, DE

*Sussex County*

Description: View of interior of lance window in third floor bedroom. Window is located in southeast front cross gable.

Photograph Number: Number seven of 7

SEP 20 1979

AUG 2 1979