

Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter Sussef County
Date: September, 1978
Location of Negative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901
Description: View of Gyles house from the west showing rear

shed.

SEP 2 5 1979

Photograph Number: 1 of 13

DV 1.3 1979



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter Sussef County

Date: September, 1978

Location of Nocative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901 Description: Closer view of end of house.

SEP 2 5 1979

Photograph Number: 2 of 13



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter Sussef County

Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs,

B/ASHP, Hall of Records, Dover, Delaware 19901

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Gable end showing lean-to addition and shed at rear.

**SEP** 2 5 1979

Photograph Number: 3 of 13

NOV | 3 1979




Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter Sussef County Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Two story wing on east end of house.

Photograph Number: 4 of 13



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter Dussif County
Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of stuccoed chimney and gable end.

SEP 2 5 1979

Photograph Number: 5 of 13

1.3 1979



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter Sussey County
Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of front porch and shingle walls.

SEP 2 5 1979

**Des**cription: Detail of front porch and shingle walls.

Photograph Number: 6 of 13

200



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter

Quasef County

Date: September, 1978

Location of Norative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901
Description: Dining room fireplace and panelling.

SEP 2 5 1978

Photograph Number: 7 of 13

1 3 10

NOV | 3 1979



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter Sussef County

Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Bedroom end wall in room over dining room, showing enclosed attic stair and enclosed lower stair at right.

CFP 2 5 1070

Photograph Number: 8 of 13



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter

Date: September, 1978 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Brick Milk House

9 of 13 Photograph Number:

SEP 2 5 1979



Trap Bond Road, Georgetown, Delaware Location:

Photographer: Richard Carter

Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: View of barn

SEP 2 5 1979

Sussef County

Photograph Number: 10 of 13



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter

Sussef County

Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: View of barn and shed of granary.

Photograph Number; 11 of 13

SEP 2 5 1979



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter

Sussef County

Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of shed framing showing braced frame and hand-hewn beams

**SEP 2 5 1979** 

Photograph Number: 12 of 13



Location: Trap Pond Road, Georgetown, Delaware

Photographer: Richard Carter

Date: September, 1978

Location of No ative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of REcords, Dover, Delaware 19901

Description: Detail of shed framing

SEP 2 5 1979

Photograph Number: 13 of 13

1 3 1979