



3-29-5 ACHS

Brach-Coover house, 1978  
Southeast elevation

FEB 1 1978

JUL 24 1978

Photo #1

Brach-Coover House, Hastings, Nebraska  
Michael Shonsey, Adams County Historical  
Society, 1978 (3-29-5), Adams County  
Historical Society.  
View to the northwest.

*Adams*



3-50-7 ACHS PC

Living room of the Brach-Coover house, 1978

Photo #2

JUL 24 1978

Brach-Coover House, Hastings, Nebraska.  
Michael Shonsey, Adams County Historical  
Society, 1978 (3-50-7) Adams County  
Historical Society.

View looking from parlor into dining room.

FEB 1 1979

*Adams Co*



7805/2:33

1682-25

RBD.4

SPe-1

FEB 1 1979

JUL 24 1978

Photo #3 *Adams*  
Brach-Coover House, Hastings, Nebraska  
D. Murphy, Nebraska State Historical Society  
May, 1978. (7805/2:31). View to the west.



7805/2:31

LCR1-30

RGP4 Spec 1

Photo #4 FEB 1 1979 JUL 24 1978  
Brach-Coover House, Hastings, Nebraska  
D. Murphy, Nebraska State Historical Society.  
May, 1978. (7805/2:31). View to the west.  
*Adams*





7805/2:35  
1082-18  
RRB4  
Spec 1

Photo #5 **FEB 1 1979**  
Brach-Coover House, Hastings, Nebraska  
D. Murphy, Nebraska State Historical Society  
May, 1978. (7805/2:35)  
View to the north-northwest. **JUL 24 1978**  
*Adams*



7805/2:34

1681-20

610 Sky  
10 Fair

R3D4

Spec 1

Photo #6 *Adams* JUL 24 1978  
Brach-Coover House, Hastings, Nebraska  
D. Murphy, Nebraska State Historical Society.  
May, 1978. (7805/2:34). View to the southeast.



7805/2:36  
LC81-25  
R804  
Spec 1

Photo #7 FEB 1 1979 JUL 24 1978  
Brach-Coover House, Hastings, Nebraska  
D. Murphy, Nebraska State Historical Society.  
May, 1978. (7805/2:36). View to the northeast.  
*D. Murphy*



7805/2:37  
1C132-23  
R1304  
SPEC1

Photo #8 FEB 1 1979  
Brach-Coover House, Hastings, Nebraska  
D. Murphy, Nebraska State Historical Society.  
May, 1978 (7805/2:37). Front porch detail.  
View to the west.

*Adams CW*

JUL 24 1978

#8