

Benton County National Bank Building, CORVALLIS, Oregon.



*Reproduced from tinted postcard  
printed - 1907 - 1910*

- 1) Benton County State Bank Building
- 2) Corvallis, Oregon
- 3) unknown
- 4) 1909
- 5) unknown
- 6) from Southwest corner of 2 nd and Madison Streets.
- 7)

MAR 7 1979

copy of a tinted postcard printed in Germany  
FEB 5 1979

Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

1 of 12  
Historic postal card, view  
ca. 1909  
West and South faces showing

original ground story outer  
end bay treatment and corner  
bay entry.

Wallace C. Weltzin  
Horner Museum  
Oregon State University  
Corvallis, OR 97330



Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

**FEB 5 1979**

2 of 12

West elevation, showing re-  
modeled outer end bay treat-  
ment and conversion of corner  
bay entry to window.

(Steps were removed from  
corner ca. 1920-1925.)

**MAR 7 1979**

State Historic Preservation  
Office photo 1978  
Salem OR 97310



Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

FEB 5 1979

3 of 12

MAR 7 1979

West and south elevations,  
showing remodeled outer end  
bays and corner bay  
treatment.

State Historic Preservation  
Office photo 1978  
Salem OR 97310



Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

**FEB 5 1979**

4 of 12 **MAR 7 1979**

Looking northeast along 2nd  
Street, showing bank building  
in relation to other struc-  
tures on the block.

State Historic Preservation  
Office photo 1978  
Salem OR 97310



TRINER & BRYSON  
LAWYERS.

BARBER SHOP

IDES

GREEN STORE

- 1) Benton County State Bank Building
- 2) Corvallis, Oregon
- 3) unknown
- 4) 1910
- 5) O.S.U. Archives
- 6) from Southwest corner of 2 nd & Madison Street.
- 7)

*BENTON CO.*

MAR 7 1979

# 51712

Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

5 of 12  
Historic view, ca. 1910  
Note basement openings.  
Main floor was lowered  
between 1920 and 1925.

Oregon State University  
Library  
Corvallis, OR 97330

FEB 5 1979



- 1) Benton County State Bank
- 2) Corvallis, Oregon.
- 3) Sidney Trask
- 4) c. 1916
- 5) glass plate O.S.U. Archives.
- 6) from Northwest side of 2 nd Street.
- 7)

MAR 7 1979

FEB 5 1979

Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

6 of 12  
Sidney Trask photo, ca. 1916  
West face, showing window  
treatment and cast metal name  
plates strapped to porch  
columns. Wood frame building  
on opposite side of Madison  
Street is Occidental Hotel,  
predecessor of existing  
Corvallis Hotel.



- 1) Benton County State Bank Building
- 2) Corvallis, Oregon
- 3) Jeff Goldner, Sun Star photographers.
- 4) September, 1978
- 5) MAR 7 1979
- 6) from Southwest corner of 2 nd & Madison Avenue
- 7)

FEB 5 1979

MAR 7 1979

Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

7 of 12  
West and south elevations

Jeff Goldner photo, 1978  
Sun Star Photographers  
Corvallis, OR 97330



- 1) Benton County State Bank Building
- 2) Corvallis, Oregon
- 3) Jeff Goldner, Sun Star Photography
- 4) September 1978
- 5)
- 6) from the Northwest side of 2 nd Street
- 7)

*Benton County*

*#8 of 12*

FEB 5 1979

MAR 7 1979

Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

8 of 12  
West elevation

Jeff Goldner photo, 1978  
Sun Star Photographers  
Corvallis, OR 97330



- 1) Benton County State Bank Building
- 2) Corvallis, Oregon
- 3) Jeff Goldner, Sun Star photographers
- 4) September, 1978

MAR 7 1979

5)  
6) from the south

7)

#9 of 12

FEB 5 1979

Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

9 of 12  
South elevation

Jeff Goldner photo, 1978  
Sun Star Photographers  
Corvallis, OR 97330



- 1) Benton County State Bank Building
- 2) Corvallis, Oregon
- 3) Jeff Goldner, Sun Star Photography
- 4) September, 1978
- 5)
- 6) from the south showing east side Alley
- 7)

FEB 5 1979

Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

10 of 12  
East (rear) elevation on  
alleyway.

Jeff Goldner photo, 1978  
Sun Star Photographers  
Corvallis, OR 97330

MAR 7 1979



- 1) Benton County State Bank Building
- 2) Corvallis, Oregon
- 3) Jeff Goldner, Sun Star photographers
- 4) September, 1978
- 5)
- 6)
- 7)

interior view of hall in second floor.

MAR 7 1979

Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

11 of 12  
Rehabilitated second story  
hallway (looking West) showing  
restoration of wainscoting,  
ceiling and skylight molding;  
preservation of existing window  
and door trim.

FEB 5 1979

Jeff Goldner photo, 1978  
Sun Star Photographers  
Corvallis, OR 97330



- 1) Benton County State Bank Building
- 2) Corvallis, Oregon
- 3) Jeff Goldner, Sun Star Photographers
- 4) September, 1978
- 5)
- 6) from the east looking west 2nd Floor interior hall

MAR 7 1979

Benton County State Bank  
Building  
Corvallis, Benton County,  
Oregon

12 of 12  
Rehabilitated second story  
hallway (looking east), showing  
restoration of wainscoting  
and moldings; preservation of  
existing window and door trim.

FEB 5 1979

Jeff Goldner photo, 1978  
Sun Star Photographers  
Corvallis, OR 97330