



#1 of 3  
Sioux Falls National Bank Bldg.  
100 N. Phillips Ave. *Minnehaha*  
Sioux Falls, SD *County*  
MAR 7 1979 JAN 22 1979

South and West faces after completion of exterior restoration in September, 1978.

*South & West Sides  
of 100 No. Phillips  
Building - Exterior  
Restoration Complete  
September, 1978*

© Stephen Parezo photog.



#20p2

MINNEAPOLIS Co

Sioux Falls National Bank Building

Sioux Falls, South Dakota

MAR 7 1979

Historical Preservation Center Staff

December 1, 1978

Negative at Historical Preservation Center

Vermillion South Dakota

Camera facing East

JAN 22 1979



10/04/78

# 3083

Sioux Falls National Bank Bldg.  
100 N. Phillips Ave. *MINNEHaha*  
Sioux Falls, SD *County*

MAR 7 1979

Sioux Falls National Bank Building

Sioux Falls, South Dakota

JAN 22 1979

Dr. Gary Olson

September 1978

Negative held by Dr. Gary Olson

Camera Facing NW

North and West faces after completion of exterior restoration in September, 1978.