TRIMBORN FARM, 8801 W. Grange Ave., Greendale, Milwaukee Co., WI, 1979. Photo by Terry Shoptaugh. Neg. at State Historical Society of Wis. View from southeast showing, l to r, old sheds, stone barn, silos, and stable. Supplemental photo #1 of 7.

CIRCLE H

TRIMBORN FARM, 8801 W. Grange Ave., Greendale, Milwaukee Co., WI, 1979. Photo by Terry Shoptaugh. Neg. at State Historical Society of Wis. Stable, photographed from north. Supplemental Photo #2/~~of 2~~.

TRIMBORN FARM, 8801 W. Grange Ave., Greendale, Milwaukee Co., WI, 1979. Photo by Terry Shoptaugh. Neg. at State Historical Society of Wis. Remains of smokehouse photographed from SW. Supplemental photo #3/7 ~~of 3.~~

JUL 31 1980

TRIMBORN FARM, 8801 W. Grange Ave.,
Greendale, Milwaukee Co., WI, 1979.
Photo by Terry Shoptaugh. Neg. at
WI Hist. Society. Farmhouse viewed
from west. Photo #4 of 4/7 MAY 20 1980

TRIMBORN FARM, 8801 W. Grange Ave.,
Greendale, Milwaukee County, WI.
Photo by Terry Shoptaugh, 1979.
Neg. at WI Hist. Society. South
lime kiln photographed from north-
east. Photo #4 of 5/7 MAY 20 1980

NO
ENTRY

TRIMBORN FARM, 8801 W. Grange Ave.,
Greendale, Milwaukee Co., WI.
Photo by Terry Shoptaugh, 1979.
Neg. at WI Hist. Society. Stone
Barn photographed from northeast.
Photo #~~3 of 4.~~ 4/4

MAY 20 1980

MAY 2 0 1980

TRIMBORN FARM, 8801 W. Grange Ave., Greendale, Milwaukee Co., WI, 1979. Photo by Terry Shoptaugh. Neg. at WI Hist. Society. Bunkhouse photographed from north. Photo #~~2 of 4~~ 2/3