

Photo 1078 View of south and west facades of Canton Hotel.

JAN 23 1980



Photo 2078

1920s photograph of south & west facades of Canton Hotel.

JAN 23 1980



Photo 3 *JS* Detail of main entrance on south elevation showing Flemish bond brickwork and panelled door jamb. JAN 2 3 1980



Photo 4 of View of north & west elevations showing where frame ell was attached to building.



Photo 5 of S Interior view showing panelled double doors on south side and transom.



Photo 6 7 8 Interior view showing stairs & addition of bathroom at rear of hall.



Photo 7 7 8 Detail of mantle in southeast room. JAN 23 1980



Photo 8 % Mantle in second floor southwest room.

JAN 23 1980