UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR NPS USE ONLY

RECEIVED AUG 1 1979

DATE ENTERED JUN 1 6 1980

SEE	INSTRUCTIONS IN HOW TO TYPE ALL ENTRIES O			3	
1 NAME	TYPE ALL ENTRIES C	OWIFLETE APPLICABL	E SECTIONS		
INVIAIT					
HISTORIC	,				
Garvin Rock	Church				
AND/OR COMMON					
Old Rock Chu	ıren				
2 LOCATION	J				
STREET & NUMBER					
	174 ama Stanota		NOT FOR PUBLICATION		
CITY, TOWN	Lliams Streets		CONGRESSIONAL DISTRICT		
Gamrin		VICINITY OF	No. 3		
STATE		CODE	COUNTY	CODE 089	
Oklahoma		40	McCurtain	nóà:	
3 CLASSIFIC	CATION				
CATEGORY	OWNERSHIP	STATUS	PRESI	ENTUSE	
DISTRICT	PUBLIC	X OCCUPIED	AGRICULTURE	MUSEUM	
EBUILDING(S)	∡ PRIVATE	UNOCCUPIED	COMMERCIAL	PARK	
STRUCTURE	вотн	WORK IN PROGRESS	EDUCATIONAL	PRIVATE RESIDENCE	
SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	RELIGIOUS	
OBJECT	IN PROCESS	YES: RESTRICTED	GOVERNMENT	SCIENTIFIC	
e	BEING CONSIDERED	XYES: UNRESTRICTED	_INDUSTRIAL	_TRANSPORTATION	
		_NO	MILITARY	OTHER:	
4 OWNER O	F PROPERTY				
NAME					
First Baptia	st Church				
STREET & NUMBER					
				····	
CITY, TOWN		Manua	state Oklahom a		
Garvin		VICINITY OF	OKLANOMA		
5 LOCATION	N OF LEGAL DESCR	IPTION			
COURTHOUSE,					
REGISTRY OF DEEDS	ETC. Office of the Cou	inty Clerk			
STREET & NUMBER					
McClain Cour	nty Courthouse				
CITY, TOWN			STATE		
Idabel			Oklahoma		
6 REPRESEN	ITATION IN EXIST	ING SURVEYS			
TÎTLE					
	mprehensive Survey				
DATE	browntio out iel				
1979		FEDERAL X	STATECOUNTYLOCAL		
DEPOSITORY FOR					
SURVEY RECORDS	Oklahoma Historical	Society			
CITY, TOWN		and which is the state of the s	STATE		
Oklahoma Ci	ty		Oklahoma		



CONDITION

CHECK ONE

CHECK ONE

__EXCELLENT

__DETERIORATED

__UNALTERED

X_ORIGINAL SITE

__GOOD

__RUINS
__UNEXPOSED

x.ALTERED (somewhat)

__MOVED

DATE____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Garvin Rock Church was an impressive affair when erected in 1910 in a town that could count only a few hundred people. Despite the loss of its stained glass windows the church remains so today ... roughly 44×64 feet over all, with a full basement and, not one, but three square crenelated towers. The largest of these stands 25 feet tall at the principal corner entry to the church. All three guard entrances to the 33×53 -foot sanctuary, at the head of long flights of concrete steps. Otherwise the church, with its towers and thick load-bearing walls, is constructed entirely of a slightly reddish-hued native limestone quarried less than a mile northeast of the site.

The prime construction contract was for \$12,000. But this did not include the stained glass windows, installed in two attractively designed banks of four long center-hung sashes (see Photo No. 1) on the south and west elevations of the church. Unfortunately, storm damage in the 1920s led to removal of these panels. Lost was the quatrefoil tracery in the two arches as well. Plain painted wood now fills in the arch above conventional sash windows.

Otherwise, however, the church remains much as it was when completed in 1910 (although the basement is no longer used). Sunday school classroom space is provided by a 20 x 30-foot section of the sanctuary that can be closed off with folding doors and by four small rooms lining the east and north walls of the church. Interior walls throughout are plastered and painted.

8 SIGNIFICANCE

SPECIFIC DATES		BUILDER/ARCI		C. Morris		
		INVENTION	Arch.: Campbell & Owens Paris, Texas			
<u>X</u> 1900-	COMMUNICATIONS	INDUSTRY	POLITICS/GOVERNMENT	OTHER (SPECIFY)		
1800-1899	COMMERCE	EXPLORATION/SETTLEMENT	PHILOSOPHY	TRANSPORTATION		
1700-1799	ART	ENGINEERING	MUSIC	THEATER		
1600-1699	ARCHITECTURE	EDUCATION	MILITARY	SOCIAL/HUMANITARIAN		
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE		
1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	LAW [.]	SCIENCE		
PREHISTORIC	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	LANDSCAPE ARCHITECTURE	X RELIGION		
PERIOD	AREAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW					

STATEMENT OF SIGNIFICANCE

Significance of the Garvin Rock Church lies in its unusually elaborate deisgn, for a relatively small church in a tiny rural community, and in its use of a native stone quarried near the site. Worth noting, too, is the fact that the church is still in regular use after nearly 70 years - though the town of Garvin now has a population of only 117 - and is, in fact, the second oldest in McCurtain County. The only one older: Wheelock Church, the state's oldest and itself in the National Register since 1972.

In 1909 Garvin was a thriving community with substantial homes, brick business buildings, and several small industries. For a time it had been the county's largest town and served as provisional county seat. The First Presbyterian Church was then housed in a small wooden building. Claude Gamble, a prominent Garvin merchant and banker, donated the lot for the new church, with the stipulation that it be "equal to that of any church in this area." It was.

Three architectural firms competed for the design contract. Campbell and Owens of Paris, Texas, won it and called for use of the local stone. A construction contract was won by M. C. Morris of Sapulpa, Oklahoma, with a bid of \$12,000. Two church members pledged the additional funds needed for the two banks of stained glass windows (see No. 7), easily the buildings most distinguishing feature.

Construction began February 15, 1910, with excavation for the full basement. Cornerstone was laid July 4, 1910. Johann Schmidtt of Little Rock, Arkansas, fabricated and installed the leaded, stained glass windows. The virtually completed building was first used in December 1910. Furnishings included pews of seasoned mulberry wood and a circular walnut pulpit. The Garvin Graphic proudly described it as "absolutely the finest church building that you will find between Fort Smith, Ark., and Dallas, Tex."

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Materials researched by the McCurtain County Historical Society ACREAGE NOT VERIFIED


ALKEAGE NOT VERIFIED

	IIIM	MAI APLIAN		
10 GEOGRAPHICAL DA	TA	Lo	ng.: 94° 56° 27°	2
	ng.: 94° 56° 27° 7 t.: 33° 57° 18° /	Ś		
ACREAGE OF NOMINATED PROPERTY	less than I acre	-		
QUADRANGLE NAME Garvin UTM REFERENCES	· · · · · · · · · · · · · · · · · · ·		QUADRANGLE SCALE	7.5 minutes
^ <u> </u>	NORTHING	B ZONE D	EASTING NORT	HING
ELJ []		FL	لبا لسليا	
GLI LILI L		нЦЦ	ليا لتبايل	
VERBAL BOUNDARY DESCRIPT	ION			the second second
Lot 4, Block 19, Original	inal Town of Gar	vin.		
				•
LIST ALL STATES AND CO	UNTIES FOR PROPERT	IES OVERI APPIN	G STATE OR COUNTY POL	INDARIES
LIGHTLE STATES AND CO	OTTICO FOR FROI ENTI	ILO OVEREALI'IN	STATE OF COUNTY BUT	MUANIES
STATE	CODE	COUNTY		CODE
STATE	CODE	COUNTY	in the second se	CODE
11 FORM PREPARED BY NAME / TITLE Kent Ruth, Deputy	Y			
ORGANIZATION			DATE	d d
Oklahoma Historical S	ociety		April 1979	
STREET & NUMBER			TELEPHONE	
Historical Building		*	405/884-54	56
CITY OR TOWN		•	STATE	
Oklahoma City			0klahoma	
12 STATE HISTORIC PR	TED SIGNIFICANCE OF	THIS PROPERTY	WITHIN THE STATE)N
NATIONAL	STATI	E	(LOCAL	
As the designated State Historic Prese hereby nominate this property for inc criteria and procedures set forth by the	lusion in the National R			
STATE HISTOPIC PRESERVATION OF FICE	R SIGNATURE			10 00
TITLE / arry X. 1	JULIANOO	M. W	DATE /	13-17
FOR NPS USE ONLY) I HEREBY CERTURY THAY THIS PR	OPERTY IS INCLUDED I	N THE NATIONA	L REGISTER	
, Bucha /s	Burd		DATE 6/	6/50
ATTENT7 // /1	EGISTEM		F //	1-
ATTEST: Bell Greatene			DATE 6/4	180
CHEF OF RECISTRATION				

Form No. 10-300a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



CONTINUATION SHEET

ITEM NUMBER 8

PAGE

1

Garvin Rock Church

Unfortunately, a severe storm in the early 1920s so damaged the stained glass windows that they had to be replaced by more conventional sashes. By this time the timber industry on which the Garvin area largely depended was in a sharp decline, as was the town's population. As the congregation lost membership, the Presbyterians finally sold the Rock Church (in October 1933) to the Baptist congregation that uses it today. The group hopes not only to preserve and maintain the still rather striking structure, but in time, perhaps even to replace its two handsome stained glass windows.