



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (1 of 13): Entrance to the  
Hambidge Center; photographer facing  
northeast.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (2 of 13): Rock house (left),  
spring house (center), Weave Shed (right):  
photographer facing northeast.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (3 of 13): Rock house;  
photographer facing northeast.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (4 of 13): Weave Shed (left),  
Dairy Barn (right), Weave and Exhibition  
Hall (background), photographer facing  
northeast.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (5 of 13): Weave Shed, interior; photographer facing northeast.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (6 of 13): Hambidge Cottage;  
photographer facing northeast.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (7 of 13): Hambidge Cottage;  
photographer facing northwest.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (8 of 13): Hambidge Cottage,  
interior; photographer facing southwest.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (9 of 13): Hambidge Cottage,  
interior; photographer facing northeast.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (10 of 13): Pavilion;  
photographer facing northeast.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (11 of 13): Foxfire Studio;  
photographer facing northeast



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (12 of 13): Dairy Barn (center)  
Milking Shed (right), Weaving and Exhibi-  
tion Hall (left); photographer facing  
northeast.



HAMBIDGE CENTER

Dillard vicinity, Rabun County, Georgia

Photographer: James R. Lockhart

Negative Filed: Georgia Department of  
Natural Resources

Date: March 1981

Description (13 of 13): Barker's Creek  
Mill; photographer facing southeast.