



AP. P. JOHNSON HOUSE, 3455 S. Shore  
Dr., Delavan, Walworth Co., Wisc.  
Photo by Chas. Quagliana, AIA, Sept.  
1980 - neg. in his possession.  
Facing SE. Photo #1 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore  
Sr., Delavan, Walworth Co., Wisc.  
Photo by Diane H. Filipowicz, Oct.  
1981. Neg. at WI Hist. Society.  
Facing NW. Photo #2 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore  
Dr., Delavan, Walworth Co., Wisc.  
Photo by Chas. Quagliana, AIA, Oct.  
1982 - neg. in his possession.  
Facing NW. Photo #3 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore  
Dr., Delavan, Walworth Co., Wisc.  
Photo by Chas. Quagliana, AIA, Sept.  
1980 - neg. in his possession.  
Site, facing SW. Photo #4 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas. Quagliana, AIA, Jan. 1981 - neg.  
in his possession. Interior living  
space, facing NW. Photo #5 of 14.



A.P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas. Quagliana, AIA, Jan. 1981 -neg.  
in his possession. Detail: fireplace,  
living space. Photo #6 of 14.

10



A. P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas. Quagliana, AIA, April 1982 - neg.  
in his possession. Detail: new fire-  
place, living space. Photo #7 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas, Quagliana, Oct. 1982 - neg. in  
his possession. Interior: living space  
after rehabilitation. Photo #8 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas. Quagliana, Oct, 1981 - neg. in  
his possession. Interior: stair during  
remodeling (previously closed). Photo  
#9 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas. Quagliana, April 1982 - neg. in  
his possession. Interior: stair after  
remodeling. Photo #10 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas. Quagliana, April 1982 - neg. in  
his possession. Interior: kitchen after  
remodeling. Photo #11 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas. Quagliana, April 1982 - neg. in  
his possession. Interior: master bedrm.  
after remodeling. Photo #12 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas. Quagliana, April 1982 - neg. in  
his possession. Interior: bedroom after  
redecorating. Photo #13 of 14.



A. P. JOHNSON HOUSE, 3455 S. Shore Dr.,  
Delavan, Walworth Co., Wisc. Photo by  
Chas. Quagliana, April 1982 - neg. in  
his possession. Interior: bathroom  
after remodeling. Photo #14 of 14.