

Photo credit: Unknown
Date of photo: Ca. 1915
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

South and east facades, looking northwest.

Photo 1 of 11



Photo credit: Bonnie J. Halda
Date of photo: December 6, 1979
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

South and east facades, looking northwest.

Photo 2 of 11



Photo credit: Bonnie J. Halda Date of photo: December 6, 1979 Location of negative: State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

East facade and north elevation, looking southwest.

Photo 3 of 11



Photo credit: Bonnie J. Halda
Date of photo: December 6, 1979
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View of lobby, looking southeast to canted entrance.

Photo 4 of 11



Photo 5 of 11

Photo credit: Bonnie J. Halda
Date of photo: December 6, 1979
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View of lobby main desk, looking north.



Photo credit: Bonnie J. Halda
Date of photo: December 6, 1979
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Photo 6 of 11

Fireplace, lobby, south wall.



Photo credit: Bonnie J. Halda
Date of photo: December 6, 1979
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View of main stair from lobby, looking west.

PHoto 7 of 11



Photo credit: Bonnie J. Halda

Date of photo: December 6, 1982

Location: of negative: State Historical Society of North Dakota

North Dakota Heritage Center

Bismarck, ND 58505

View of dining room doors, looking west from lobby.

Photo 8 of 11



Photo credit: Bonnie J. Halda
Date of photo: December 6, 1979
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Dining room, looking west.

Photo 9 of 11




Photo credit: Bonnie J. Halda
Date of photo: December 6, 1979
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Photo 10 of 11

Typical hotel room.



Photo credit: Bonnie J. Halda
Date of photo: December 6, 1979
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Garage

Photo 11 of 11