United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

received JN 9 1983
date entered

See instructions in *How to Complete National Register Forms*Type all entries—complete applicable sections

Type all entries	s—complete appl	icable se	ctions			
1. Nam	10					
historic Sci	ola Missionary	, Baptis	st Church	† . •	•	
and/or common	Sciola Commu		*			
2. Loca		inity of	·			
street & number	on U/S/71	. at Sci	ola (Section 16,	T-72-N, R- 3 6-W)	not for publication	
city, town			vicinity of			
state	Iowa	code	019 county	Montgomery	code 137	
3. Clas	sificatio	n				
Category district x building(s) structure site object	Ownership _x_ public private both Public Acquisit in process being considen/a/		Status XX occupied unoccupied work in progress Accessible yes: restricted XX yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence xx religious scientific transportation other:	
4. Own	er of Pro	pert	y		•	
name Was	hington Townsh	ip (c/o	E. Artlip)			
street & number	Route 2					
city, town	Villisca		vicinity of	state	Iowa 50864	
5. Loca	ation of L	ega.	l Description	on		
courthouse, regi	stry of deeds, etc.	Count	y Clerk's Office			
street & number		Montg	omery County Court	chouse		
city, town		Red O	ak	state	Iowa 51566	
6. Rep	resentat	ion i	n Existing S	Surveys		
title n.a	a		has this pro	perty been determined elig	gible? yes no	
date				federal state	e county local	
depository for su	urvey records					
city, town				state		

7. Description

excerrent	ruins	Check one unaltered xx altered	Check one original sitexx moved date	1970
fair	unexposed			

Describe the present and original (if known) physical appearance

Sciola Missionary Baptist Church is a very early (1871) surviving vernacular frame church building. It is visually more representative of its 1892 remodeling. The Sciola Church is rectangular on plan (28' x40') with gable roof. Originally the clapboarded church had four evenly spaced narrow double hung sash (4/4) windows on each side, a single window and a door with stoop and transom on the rear wall, and two doors with transoms on the front. Plain wooden surrounds and pedimented headings decorated each door and window.

An April 1892 windstorm damaged what is now the west side of the church and required a general rebuilding that same year. The damaged wall's fenestration was altered so that only the right-hand window remained unchanged in its location, and a three window grouping replaced the other windows. This grouping consists of a central window flanked by slightly shorter windows, all of which are surrounded by a flared "hour glass" shaped panel of cove butt cut wooden shingles. The main facade was altered by the enlargement of the left hand door to a double door, the addition of a dentiled heading, and by the replacement of the remaining door with a window. The rear window was sealed off. The chimney was relocated from the front of the ridgeline to a point west of the ridgeline and in front of the balcony. A narrow horizontal balcony window was added to the west facade beneath the eavesline in 1922.

The present church was last altered in 1970 when the building was moved, the chimney was replaced, and a basement of concrete block construction raised the building by a few feet. The church originally was based on red sandstone blocks. An exterior storm cellar entrance was also added. The church (refer to 1908 photo) was originally on a slightly sloping site with the rear door requiring a wooden stoop. The moving of the church has raised the building only in the front. Original plaster walls and ceiling were lost during the relocation. Baseboard and quarter round woodwork were also lost at this time.

Inside the church, the original pews, pulpit, inner double doors (1892) all survive and are of importance. A kitchen was added behind the sancturary in recent years.

8. Significance

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799 1800–1899 1900–	Areas of Significance—C archeology-prehistoric archeology-historic agriculturexx architecture art commerce communications	theck and justify below community planning landscape architectu conservation law economics literature education military engineering music exploration/settlement philosophy industry politics/government invention	re religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	1871–1929	Builder/Architect Unknown	

Statement of Significance (in one paragraph)

Sciola Missionary Baptist Church is the only remaining building from the community of Sciola, Washington Township, Montgomery County. As such, it survives, despite alterations and a minimal relocation, as a rare example of an early lowa frame church building.

The Sciola Post Office was established March 2, 1855 as the first post office in the county, and finally was closed on June 30, 1905. Sciola appears to have been a small country crossroads settlement, being composed of a few stores, this church, and the post office. The center served as a township focal point during the early settlement and Civil War years. The Union Leage of America for example reported forty-seven members at Sciola as of October 1864. A local grange was centered here as of 1874.

The Sciola Missionary Baptist Church was organized in January 1869 with nine member families. John Yergey, a member, sold land to the congregation in June 1871 (and again in 1882 for cemetery space). The building was dedicated June 30, 1872, and cost \$1,600 to build. By 1881 average attendance at services was forty-five. The church usually shared a minister with Baptist churches in Grant and Villisca in neighboring townships. The church was always economically marginal but survived until mid-1929. In 1896 part of the cemeterey was sold off and a store occupied that site. The church filled an important area function, housing Farm Bureau, 4-H, and similar needs.

This community service tradition continued when in 1946 the newly formed Sciola Community Church rededicated the building for its use. General elections, AAA, soil conservation, telephone board, school board, and 4-H township functions were all allowed to use the building. The use of the building for elections was recently resumed and takes place in the basement. Voting at this location was discontinued when the church was relocated in 1970. The church has been in township ownership since 1980, ten years after local efforts to save the church began.

The church was originally located on the east end of the present property, in close proximity to the highway right of way. The present day southern facade then faced east. The building was moved to the rear (west end) of the lot and reoriented 90 degrees to the south in order to save it from highway development in 1970.


9. Major Bibliographical References

Refer to Continuation Sheet 9-2

10. Ge	ograp	hical	Data	<u> </u>				
Acreage of nom	inated propert	y <u>less</u>	than on					1/2/ 000
Quadrangle nan UTM References		MIIIS				Quadrang	le scale	1/24,000
	3,070,	. 4 5 4 4	2 4 0		Ві ііі			1
Zone East		Northing	لب	•		ting	Northing	
	لتبلي		لبيا		D			
للا ليا ا		لسلسا			F L L			
للا ليا:					н 🔟 📙			
of the Sou	at a point theast Qua	which is	7 rods ec. 16	north of T-72-N, R	R-36-W, 5th	P.M., then	ce north . of beg	Northeast Quart seven rods, inning, includi
List all states	and countie	s for prope	rties ove	erlapping s	tate or count	y boundaries		cch and excludi
state n.	a	•	code	count	y		A wo code	n outhouse is i
tate			code	count	:v		code	l but is intrus
rganization	James E. J Iowa SHPO Historical	· · · · · · · · · · · · · · · · · · ·		l Registe	er Coordinat	:	25, 1983	
treet & number	F 12+b &	_			teleph	one 515-	281-4137	
Ity or town	Des Moines				state	Iowa	50319	
12. Sta	ate His	toric	Pres	servat	tion Of	ficer C	ertifi	cation
he evaluated si	ignificance of	this property	within the	e state is:		-		
	national	s	tate	<u>xxx</u> ¥6cal				
As the designate 665), I hereby no according to the State Historic Pr	ominate this pr criteria and p	roperty for in rocedures s	nclusion in et forth by	the Nationa	Register and	certify that it h		
itle Execut	ive Direct	or Iowa S	State Hi	storical	Department	date	May 25	, 1983
For NPS use	only ertify that this	property is i	ncluded in	the Nationa	l Register		11	
1 Beth 6	morvens					date	7/18/83	
Keeper of the	e National Re	gister						
Attest:						date	The second	
Chief of Reg	istration							

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form



Continuation sheet Bibliography

item number

9

Page

2

Merritt, W. W. A History of the County of Montgomery. Red Oak: Express Publishing Company, 1906, pp. 260, 542.

History of Montgomery County, Iowa. Des Moines: Iowa Historical and Biographical Company, 1881, pp. 542, 544.

The Independent, 1887-1893.

The Red Oak Express . 1874-1981.

The Villisca Review. 1871-1981.

Montgomery County Land Records.

Sciola Community Church Minute Book.