



Photo #10 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
February, 1983 (NSHS 8302/7:15)

General view looking northwest showing
parishioner's house in foreground and
"beer shack" in rear.



Photo #1 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
February, 1983 (NSHS 8302/7:32)

General view looking southwest showing
church, rectory and cemetery.



Photo #2 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
February, 1983 (NSHS 8302/7:2)

View looking west showing east (front)
facade of church.




Photo #3 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
February, 1983 (NSHS 8302/7:28)

View looking west showing detail of east
(front) facade of church.




Photo #4 of 14

St. Boniface Catholic Church

Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska

State Historical Society

February, 1983 (NSHS 8302/6:2)

View looking south showing detail of
north facade of church.



Photo #5 of 14

St. Boniface Catholic Church

Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska

State Historical Society

February, 1983 (NSHS 8302/7:10)

View looking southeast showing north and west facades of church.



Photo #6 of 14

St. Boniface Catholic Church

Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska

State Historical Society

February, 1983 (NSHS 8302/8:3)

Interior view of church looking west
from the nave toward chancel area.



Photo #7 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
February, 1983 (NSHS 8302/8:7)

Interior view of church looking east
from the nave toward vestibule and
balcony area.




Photo #8 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
February, 1983 (NSHS 8302/8:8)

Interior view of church looking south
showing stained glass windows in
transept area.



Photo #9 of 14

St. Boniface Catholic Church

Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska

State Historical Society

February, 1983 (NSHS 8302/7:27)

View looking northwest showing south and east facades of rectory.



ST. BONIFACE
SCHOOL



Photo #11 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
February, 1983 (NSHS 8302/7:26)

View looking east showing west (front)
facade of school.



Photo #12 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
February, 1983 (NSHS 8302/7:23)

View looking northeast showing south
and west facades of school.



Photo #14 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society

February, 1983 (NSHS 8302/7:36)

View looking west showing iron crosses
in cemetery.



Photo #13 of 14

St. Boniface Catholic Church
Complex (CD10-1)

Menominee, Cedar County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
February, 1983 (NSHS 8302/7:21)

General view looking north showing
cemetery with church in background.