



Name: Historic Resources of Centreville (N-6186)
Centreville Historic District

Location: Centreville, Delaware
Streetscape

Photographer: Richard Jett

Date: October 1980

Location of Negative: Division of Historical &
Cultural Affairs, BA&HP, Hall of Records, Dover, DE

Description: Three-quarter view of N-5826 (left) and
N-1142 (right) facing northeast.

Photograph Number: 7 of 34



Historic District of Centreville (N-6186)

Name: Centreville Historic District
Streetscape (N-5828) & (N-5827)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: October 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA & HP, Hall of Records, Dover, Delaware 19901

Description: Streetscape looking southeast along the
Kennett Pike

Photograph Number: 8 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5812 Kennett Pike,
Buckley's Tavern (N-1145), Nichols House

Location: Centreville, Delaware

Photographer: Gretchen Fitting

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Three-quarters view showing East facade and side facing
North.

Photograph Number: 9 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5810 Kennett Pike,
M. J. Furey House (Jolly Needlewoman) (N-1146)

Location: Centreville, Delaware

Photographer: Gretchen Fitting

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Three-quarters view showing facade facing East, side
and wing, South.

Photograph Number: 10 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5808 Kennett Pike,
R. T. Carey (La Cocina) (N-5285)

Location: Centreville, Delaware

Photographer: Gretchen Fitting

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Three quarter view showing facade facing South, and
side, East.

Photograph Number: 11 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5808 Kennett Pike,
R. T. Carey (La Cocina) (N-5285)

Location: Centreville, Delaware

Photographer: Gretchen Fitting

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Elevation of side and wing, facing East.

Photograph Number: 12 of 34



Historic District of Centreville (N-6186)

Name: Centreville Historic District, 5808 Kennett Pike,
R. T. Carey (La Cocina) (N-5285)

Location: Centreville, Delaware

Photographer: Gretchen Fitting

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Principal facade doorway.

Photograph Number: 13 of 34



Historic District of Centreville(N-6186)

Name:Centreville Historic District, 5804 Kennett Pike

Centreville Veterinary Hospital (N-1147), Stone

Location:Centreville, Delaware

Dwelling

Photographer:Gretchen Fitting

Date:April 1980

Location of Negative:Division of Historical and Cultural
Affairs,BA/&HP, Hall of Records, Dover, Delaware 19901

Description: View of original structure with modern
additions, facing east.

Photograph Number: 14 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5802 Kennett Pike,
Plain and Fancy (N-1148), Stone Dwelling

Location: Centreville, Delaware

Photographer: Gretchen Fitting

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Facade facing East.

Photograph Number: 15 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5800 Kennett Pike,
Frances Boutique (N-1149), Rev. D. W. Moore House

Location: Centreville, Delaware

Photographer: Gretchen Fitting

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Side elevation facing South.

Photograph Number: 16 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5800 Kennett Pike,
Frances Boutique (N-1149), Rev. D. W. Moore House

Location: Centreville, Delaware

Photographer: Gretchen Fitting

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Hexagonal addition facing Southwest.

Photograph Number: 17 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5722 Kennett Pike,
James Delaplaine House (N-1142)

Location: Centreville, Delaware

Photographer: Richard Jett


Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Facade and side elevation facing Southeast.

Photograph Number: 18 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5722 Kennett Pike,
James Delaplaine House (N-1142)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Principal facade doorway.

Photograph Number: 19 of 34



OLD DIRECTOR
MORRIS RAREY 4
P. WELMOUTH & SMITH 2
P. E. J. LAVINO 3

FRANK RAY

Name: Historic Resources of Centreville (N-6186)

Mrs. Wiggins House (N-5826)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: October 1980

Location of Negative: Division of Historical &
Cultural Affairs, Hall of Records, Dover, DE

Description: Facade and side elevation facing
southeast.

Photograph Number: 20 of 34



Frederick's

BEAUTY SALON

Fishers

bedpost

THE DRAPERY HANG UP

the horse

LAMP & SHADE

RING TO FICHEZ

Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5714-5716 Kennett
Pike, Chandler-Dixon-Frederick House (N-1143)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Facade and side elevation facing Southeast.

Photograph Number: 21 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5714-5716 Kennett
Pike, Chandler-Dixon-Frederick House (N-1143)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Side elevation and wing showing later additions as seen
from the Southwest.

Photograph Number: 22 of 34



Historic Resources of Centreville (N-6186)
Name: Centreville Historic District, 5714-5716 Kennett
Pike, Chandler-Dixon-Frederick House (N-1143)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Side elevation with detail of late 19th century bay,
facing South.

Photograph Number: 23 of 34



Historic Resources of Centreville (N-6186),

Name: Centreville Historic District, Corner of Kennett
Pike & Centre Meeting Road, Dr. Joseph H. Chandler
Location: Centreville, Delaware House

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Elevation of facade and side from the Southwest.

Photograph Number: 24 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, Corner of Kennett
Pike & Centre Meeting Road, Dr. Joseph H. Chandler
Location: Centreville, Delaware House

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Side elevation facing North.

Photograph Number: 25 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, Corner of Kennett
Pike & Centre Meeting Road, Centreville Hall

Location: Centreville, Delaware (N-1379a)

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Elevation of side and partial view of facade facing
Southwest.

Photograph Number: 26 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5723-21 Kennett
Pike (N-5827)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Front and side elevation facing West.

Photograph Number: 27 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5725 Kennett Pike,
The Odd Fellows Hall (N-5828)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical and Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Facade and side elevation facing Northwest.

Photograph Number: 28 of 34



FOUR SEASONS

PARTY SHOP

CHINA & GLASS

GIFTS & LINEN

PARTY ITEMS

CANDLES & CARDS



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5725 Kennett Pike,
The Odd Fellows Hall (N-5828)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Facade and side elevation facing Southwest.

Photograph Number: 29 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, Corner of Twaddell
Mill Road & Kennett Pike, Canby Grove Park

Location: Centreville, Delaware (N-5829)

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

View of Canby Grove park area from the Southwest.

Photograph Number: 30 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, Corner of Twaddell
Mill Road & Kennett Pike, Connor's Store (N-1377)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

View of front and side elevation facing Southwest.

Photograph Number: 31 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, Corner of Twaddell
Mill Road & Kennett Pike, Connor's Store (N-1377)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Detail of display window on South side of Connor's Store.

Photograph Number: 32 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5807 Kennett Pike,
Mrs. Todd's Residence (Witsil Residence) (N-5830)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Front and side elevation and wing facing the Northwest.

Photograph Number: 33 of 34



Historic Resources of Centreville (N-6186)

Name: Centreville Historic District, 5807 Kennett Pike,
The Carriage House (Witsil Realty Office) (N-5839a)

Location: Centreville, Delaware

Photographer: Richard Jett

Date: April 1980

Location of Negative: Division of Historical & Cultural
Affairs, BA/and HP, Hall of Records, Dover, DE 19901

Description:

Front and side elevation facing Southwest.

Photograph Number: 34 of 34