

Mary Davis, July 1980 Historic Landmarks Survey of Albuquerque

East facade 19


NOV 1 9 1980



Mary Davis, July 1980 Historic Landmarks Survey of Albuquerque

View from NE

2/9





Mary Davis, July 1980 Historic Landmarks Survey of Albuquerque

NON


3/9

View of rear section from NW



Mary Davis, July 1980 \checkmark Historic Landmarks Survey of Albuquerque


View from SE showing addition on south side 4/g



Mary Davis, July 1980 Historic Landmarks Survey of Albuquerque

T NON





6/9

Mary Davis, July 1980 Historic Landmarks Survey of Albuquerque

Detail of front door



Mary Davis, July 1980 Historic Landmarks Survey of Albuquerque

Detail of doors, north side rear section

7/9



Kathleen Brooker, June, 1980 Historic Landmarsk Survey of Albuquerque

Upstairs hall, rear section, looking west $\frac{8}{9}$



Mary Davis, July 1980 Historic Landmarks Survey of Albuquerque

Fireplace, northern room, front wing