


THE HISTORIC RESCURCES OF WAUKESHA St. Joseph's Church 818 N. East Avenue Wankesha, Wauk. Co., Wisc., Photo by E. Purcell July 1982, Neg. at Wisc. State Historical Soc. View from Southeast; Photo 1 of &



THE HISTORIC RESOURCES OF WAUKESHA St. Joseph's Church 818 N. East Avenue Waukesha, Wauk. Co., Wisc., Photo by R. Pruetz Dec. 1982, Neg. at Wisc. State Hist. Soc. Interior, Side Sanctuary window; Photo 2 of 8



## THE HISTORIC RESOURCES OF WAUKESHA St. Joseph's Church

818 N. East Avenue

Waukesha, Wauk. Co., Wisc., Photo by R. Pruetz

Interior, Altar; Photo 3 of 8

Dec. 1982, Neg. at Wisc. State Hist. Soc.



THE HISTORIC RESOURCES OF WAUKESHA St. Joseph's Church 818 N. East Avenue Wankesha, Wank. Co., Wisc., Photo by R. Pruetz Dec. 1982, Neg. at Wisc. State Hist. Soc. Interior; Side Bays Sanctuary; Photo 4 of 8



THE HISTORIC RESOURCES OF WAUKESHA St. Joseph's Complex; Rectory (non-contributing 822 N. East Avenue Waukesha, Wauk. Co., Wisc., Photo by R. Pruetz February 1983, Neg. at Wisc. State Hist. Soc.

View from Southeast; Photo 5 of 9



## THE HISTORIC RESOURCES OF WAUKESHA

St. Joseph's Church

818 N. East Avenue

Waukesha, Wauk. Co., Wisc., Photo by R. Pruetz Dec. 1982, Neg. at Wisc. State Hist. Soc. Interior: Rear Sanctuary Window: Photo 6 of 8



THE HISTORIC RESOURCES OF WAUKESHA St. Joseph's Complex: Medical Clinic 826 N. East Avenue (non-contributing) Waukesha, Wauk. Co., Wisc., Photo by R. Pruetz February 1983, Neg. at Wisc. State Hist. Soc.

View from East; Photo 7 of 8