

CEDAR


OAK

S. HARRISON


PUBLIC SCHOOL No. 19
HEAT, STEAM, NO LIGHTS, WINDOWS ALL SIDES

Photograph of Sanborn Atlas, 1901 showing Public School No. 19
Photo taken by Hagley Library of atlas in their collection

MARYLAND AV.



Photograph of Sanborn Atlas,
1927 showing Public School No. 19
Photograph taken by Hagley Library
of atlas in their collection





Public School No. 19
Photo #1
Upper floor, east facade

Name: Public School No. 19

Location: 801 S. Harrison St., Wilmington, DE

Photographer: F.M. Thompson

Date: August, 1984

Location of Negative: Design Collaborative
1211 Delaware Ave, Wilmington, De 19806

Description: Upper floor of east facade showing
hoodmoulds and date plaque

Photograph Number: |

Public School No. 19
Photo #2
Portion of North facade & wing
extending to west



Name: Public School No. 19

Location: 801 S. Harrison St., Wilmington, DE

Photographer: F.M. Thompson

Date: August, 1984

Location of Negative: Design Collaborative
1211 Delaware Avenue, Wilmington, DE 19806

Description: Portion of north facade showing
wign extending to west and entrance door

Photograph Number: 2

Public School No. 19
Photo #3
Cornice & bracket detail



Names: Public School No. 19

Location: 801 S. Harrison St., Wilmington, DE

Photographer: F.M. Thompson

Date: August, 1984

Location of Negative: Design Collaborative
1211 Delaware Ave, Wilmington, DE 19806

Description: Cornice & bracket detail

Photograph Number: 3

Public School #19
Photo #4
South and west facades



Name: Public School No. 19

Location: 801 S. Harrison St., Wilmington, DE

Photographer: F. M. Thompson

Date: August, 1984

Location of Negative: Design Collaborative
1211 Delaware Ave., Wilmington, DE 19806

Description: South and west facades

Photograph Number: 4

Public School No. 19
Photo #5
North Facade



S. MALLEVE, M.D.
E. SCHMITT, M.D.
PHYSICIANS

FOR LEASE
OFFICE
B. E. CITY
REALTY
7-3500

Name: Public School No. 19

Location: 801 S. Harrison St., Wilmington, DE

Photographer: F.M. Thompson

Date: August, 1984

Location of Negative: Design Collaborative, 1211
Delaware Ave., Wilmington, DE 19806

Description: North Facade

Photograph Number: 5



Name: Public School No. 19

Location: 802 S.Harrison St., Wilmington, DE

Photographer: Patricia Maley

Date: June, 1984

Location of Negative: Design Collaborative
1211 Delaware Ave.
Wilmington, DE 19806

Description: Top of stairwell showing entrance to
central corridor on second floor

Photograph Number: 6



Name: Public School No. 19

Location: 802 S.Harrison St., Wilmington, DE


Photographer: Patricia Maley

Date: June, 1984

Location of Negatives: Design Collaborative
1211 Delaware Ave.
Wilmington, DE 19806

Description: Lower section of east stairwell, with
door to central corridor on first floor in foreground

Photograph Number: 7



Name: Public School No. 19

Location: 802 S.Harrison St., Wilmington, DE

Photographer: Patricia Maley

Date: June, 1984

Location of Negative: Design Collaborative
1211 Delaware Ave.
Wilmington, DE 19806

Description: Interior view of northeast entrance

Photograph Number: 8



Name: Public School No. 19

Location: 802 S.Harrison St., Wilmington, DE

Photographer: Patricia Maley

Date: June, 1984

Location of Negative: Design Collaborative
1211 Delaware Ave.
Wilmington, DE 19806

Description: Stair detail

Photograph Number: 9