



Property Name: Butler House  
Location: Vicinity Avondale, Colorado  
Photographer/Date: Jim Munch/November 1983  
Negatives: Colorado Office of Archaeology  
& Historic Preservation  
Camera Direction: East elevation. Main house  
and stone agent's house  
Photo No.: 1



Property Name: Butler House

Location: Vicinity Avondale, Colorado

Photographer/Date: Jim Munch/November 1983

Negatives: Colorado Office of Archaeology  
& Historic Preservation

Camera Direction: View of main house, looking  
southwest

Photo No.: 2



Property Name: Butler House

Location: Vicinity Avondale, Colorado

Photographer/Date: Jim Munch/November 1983

Negatives: Colorado Office of Archaeology  
& Historic Preservation

Camera Direction: View of main house, looking  
northwest. Barn is visible  
in background

Photo No.: 3



Property Name: Butler House

Location: Vicinity Avondale, Colorado

Photographer/Date: Jim Munch/November 1983

Negatives: Colorado Office of Archaeology  
& Historic Preservation

Camera Direction: West elevation of house

Photo No.: 4



Property Name: Butler House

Location: Vicinity Avondale, Colorado

Photographer/Date: Jim Munch/November 1983

Negatives: Colorado Office of Archaeology  
& Historic Preservation

Camera Direction: View looking southeast.  
Stone cistern/outhouse  
seen in foreground; stone  
residence to the left.

Photo No.: 5



Property Name: Butler House

Location: Vicinity Avondale, Colorado

Photographer/Date: Jim Munch/November 1983

Negatives: Colorado Office of Archaeology  
& Historic Preservation

Camera Direction: Stone agent's house, looking  
southwest

Photo No.: 6



Property Name: Butler House

Location: Vicinity Avondale, Colorado

Photographer/Date: Jim Munch/November 1983

Negatives: Colorado Office of Archaeology  
& Historic Preservation

Camera Direction: Stone agent's house, looking  
northeast

Photo No.: 7



Property Name: Butler House  
Location: Vicinity Avondale, Colorado  
Photographer/Date: Jim Munch/November 1983  
**Negatives:** Colorado Office of Archaeology  
& Historic Preservation  
Camera Direction: Stone cistern/outhouse  
Photo No.: 8