United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

received JAN 2 4 1984 date entered

See instructions in *How to Complete National Register Forms*Type all entries—complete applicable sections

Type an entries	s—complete applicable	e sections		
1. Nam	ne			
historic Davi	s-Exchange Bank Bu	ilding		
and or common	Same			
2. Loca	ation			
street & number	100-102 N orth Wa	shington S treet	N/ <u>/</u>	1_ not for publication
city, town A1	bany	N/A_ vicinity of		
state Georg	ia co	ode 013 county	Dougherty	code 095
3. Clas	sification	_		
Category district _X building(s) structure site object	Ownership publicX private both Public Acquisition in process being considered	Status X occupied unoccupied work in progress Accessible X yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
name Dr. Jo	eff D. McGee			
street & number	1617 Valencia Dr	rive		
	bany	N/A vicinity of		Georgia 31706
5. Loca	ation of Lec	gal Descripti	Off	
courthouse, regi	stry of deeds, etc. Su	perior Court		
street & number	Dougherty Count	y Courthouse		
city, town A1	bany		state	Georgia
6. Rep	resentation	in Existing	Surveys	
title See Se	ction 7.	has this pr	operty been determined elig	gible? yes _X no
date			federal state	county local
depository for su	urvey records			
city, town			state	

7. Description

Condition excellent deteriorated ruins fair unexposed	Check one unaltered X altered	Check oneX_ original site moved date _	·
•			

Describe the present and original (if known) physical appearance

The Davis-Exchange Bank Building is a rectangular, six-story, masonry building with a flat roof designed in the commercial Georgian Revival style. It is finished in tapestry brick on its public sides and common brick on the other sides, laid as a veneer over its concrete and steel frame. The building is ornamented on two sides with string courses, decorative molded arches over the first-floor windows and doors, an elaborate cornice, and relief sculpture panels between the first two floors. The upper floors have their original windows, while replacements appear on the second and third floors. Since the building was built to house the Albany Exchange Bank, the open first floor and mezzanine reflect that purpose, while the second through sixth floors contain offices which open off both sides of an L-shaped hall. The interior walls are plaster with paneled wainscoting in the banking room. There is an original vault in the northwest section of the first floor. Much of the first floor has been remodeled over the years. The mezzanine contains plain plaster walls, a concrete floor and no unusual details. The upper floors have plaster walls, wooden doors and window trim. All office doors have sidelights filled with translucent glass. The upper hallways have chair railing. The building retains its original concealed concrete-and-steel frame. The original boiler has been converted from coal to gas. The building sits on a corner of a downtown city block in Albany, with sidewalks on two sides and adjacent commercial buildings on the other two sides. There are no outbuildings. Changes include the position of aluminum windows on the second and third floors and the remodeling of the first floor.

6. Representation in Existing Surveys

On December 30, 1982, the National Register Programs Division of the National Park Service, Southeast Regional Office, issued a preliminary certification of significance for this property.

8. Significance

1400-1499 1500-1599 1600-1699 1700-1799 1800-1899	Areas of Significance—C archeology-prehistoric agriculture architecture artX commerce communications	community planning conservation economics education engineering exploration/settlement	music	e religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	1919–21	Builder/Architect J.E.I	R. Carpenter, Archit	ect

Statement of Significance (in one paragraph)

The Davis-Exchange Bank Building is significant in architecture and commerce. Architecturally, the building is significant as the first of its style to be built in Albany, setting local precedents as a Georgian Revival commercial structure. The building had the most substantial concrete framing in Albany up to that time. It exemplified the Georgian Revival style through the use of red brick with light trim, rounded decorative arches, the modillioned cornice and inset decorative panels. Shortly afterwards, two hotels were built in Albany that were very similar in style and reflected the impact of this building. The bank building is also significant architecturally as a work of J.E.R. Carpenter (1867-1932) of New York City, who had received the American Institute of Architects' Gold Medal in 1916 and had studied in Paris at the Ecole des Beaux Arts. He is best known in the South for the Hurt Building in Atlanta and the Hermitage Hotel in Nashville. In commercial history, the building is important for having been built as the city's first skyscraper, to house the Albany Exchange Bank, one of the city's most important financial institu-It replaced the bank's earlier building, which had burned. The Albany Exchange National Bank had been organized in the late 1890s and was one of several local banks. When the new bank building opened in 1921, it also housed many important local business and professional firms besides the banking operations. The bank was purchased in 1929 by Citizens and Southern. After they moved to newer facilities, the bank area became a shoe store.

These areas of significance support property eligibility under National Register criteria A and C.

9.	Mai	or	Bib	lioa	rap	hical	Ref	eren	ces
•		•				~			

Dixon, Sandra, Erick Montgomery, and Gary Elmore, Historic Property Information Form, 1982; based on the county history, city directories, building permits, deeds, taxes, records of The Albany Herald, and Ball family records.

Carpenter, J.E.R., Architects in Georgia Research Files, Historic Preservation Section.

10	0 b :	L D - t -			
<u> 10.</u>	Geographi	cai Data		"	
Quadran	of nominated property $_$ agle name $_Albany$ We terences		<u>r</u> e	Quadr	rangle scale 1:24,000
A 116 Zone		14 9 16 8 18 10 orthing	B Zone	Easting	Northing
C E G			D		
The n		consists of that iated with the bu	uilding and	all that has	s underneath the buildi ever been associated w
	states and counties for		oping state or	county boundar	ries
itate	N/A	code	county		code
tate		code	county		code
organiza street &	,	ervation Section of Natural Resortion Street, S.W.	urces		r 19, 1983 4) 656-2840
ity or to	own Atlanta			state Georgi	a
12.	State Hist	oric Prese	rvation	Officer	Certification
	uated significance of this	state X	local		
65), I he	esignated State Historic I ereby nominate this prope ng to the criteria and proc	erty for inclusion in the	National Regist	er and certify that	n Act of 1966 (Public Law 89– it has been evaluated
State His	storic Preservation Office		eth A. Lyon	Fyon	
itle g	State Historic Pres		-	dat	e 1/6/84
For N	IPS use only				
1 h	ereby certify that this pro	perty is included in the	National Regist	er	2122/200
	uw/ du	M	·	dat	e 2/07/1984
Keep	er of the National Regist	er			,
Attes				dat	е
Uniel	f of Registration				

SKETCH MAP/PLAT MAP

DAVIS-EXCHANGE BANK BUILDING Albany, Dougherty County, Georgia

Scale: 1" = 50'

Source: Based on county tax maps

Date: c. 1982

Key: The nominated property is marked by a

heavy black line.

6/

١)					
	_					

SILVER'S 5&10 STORE		ቀ. ማ ነና <i>ነ67.</i> 3		one and the difference of the second			232.	6		
CHURCHWELL'S STORE		67.3 19.7								œ Q
GILBERG'S STORE	700 VACANT	VACANT NO	Ö	STOR E		STORE	u	ж С.		ACE
C & S. BANK BLDG. V VACANT (BANK)	(BANK) VACANT (DRIVE-IN BANK) VAC	(DRIVE-IN BANK)	GLOANS INVEST.	GOIXIE ARMY ST	SPAWN SHOP	WBEST SHOE STO	USED FURNITURE	A C. FLANCE CO.	100000	EWESTBROOK PL

83.6