Queen Bee Mill
Sioux Falls, South Dakota
Verlyn Haahr
Sept. 1983
State Historical Preservation Center
Interior, Cement Foundation, Looking East
Photo #1 of Eight

Queen Bee Mill
Sioux Falls, South Dakota
Verlyn Haahr
Sept. 1983
State Historical Preservation Center
Interior Corner of Mill, East and South Walls
Photo #2 of Eight

Queen Bee Mill
Sioux Falls, South Dakota
Verlyn Haahr
Sept. 1983
State Historical Preservation Center
Elevator Foundation, Looking East and South
Photo #3 of Eight

Queen Bee Mill
Sioux Falls, SD
Verlyn Haahr
Sept. 1983
State Historical Preservation Center
Foundation of Elevator, Looking East
Photo #4 of Eight

Queen Bee Mill
Sioux Falls, South Dakota
Verlyn Haahr
Sept. 1983
State Historical Preservation Center
Foundation, Elevator, Looking East
Photo #5 of Eight

Queen Bee Mill
Sioux Falls, South Dakota
Verlyn Haahr
Sept. 1983
State Historical Preservation Center
Foundation, Elevator, Looking NW
Photo #6 of Eight

Queen Bee Mill
Sioux Falls, South Dakota
Verlyn Haahr
Sept. 1983
State Historical Preservation Center
Mill, Looking South
Photo #7 of Eight

Queen Bee Mill
Sioux Falls, South Dakota
Verlyn Haahr
Sept. 1983
State Historical Preservation Center
Mill, West Wall
Photo #8 of Eight