

Downtown Stamford Historic District (Boundary Increase) - Stamford, CT East Side of Summer Street, Stamford Water Company, Southwest View J. Gardner, January 1984

Negative on file at Connecticut Historical Commission

Photograph #1



Downtown Stamford Historic District (Boundary Increase) - Stamford, CT East Side of Summer Street, Northwest View J. Gardner, January 1984

Negative on file at Connecticut Historical Commission

Photograph #2



Photograph #3 Downtown Stamford Historic District (Boundary Increase) - Stamford, CT East Side of Summer Street, #211, West View J. Gardner, January 1984 Negative on file at Connecticut Historical Commission



Photograph #4 Downtown Stamford Historic District (Boundary Increase) - Stamford, CT North Side of Summer Place, Southeast View J. Gardner, January 1984

Negative on file at Connecticut Historical Commission

3/4

XT YOURSELF

SACHS

115

HEATING SUPPLIES
LEADERS & GUTTERS
SHEET METAL

SACHS PLUMBING SUPPLIES

Photograph #5 Downtown Stamford Historic District (Boundary Increase) - Stamford, CT North Side of Summer Place, Goulden Warehouse, South View J. Gardner, January 1984 Negative on file at Connecticut Historical Commission



Photograph #6

Downtown Stamford Historic District (Boundary Increase) - Stamford, CT

West Side of Summer Street, Southeast View

J. Gardner, January 1984

Negative on file at Connecticut Historical Commission