

City, Village or Town: City of Wauwatosa		County: Milwaukee	Surveyor: Virginia A. Palmer	Date: May 27, 1985	Street Cedar Street
Street Address: 6839 Cedar Street, originally noted as 233 Cedar Street		USGS Quad and UTM Reference: 16/418820/4765600		Acreage: less than 1	
Current Name & Use: private residence		Current Owner: Janet M. Jelinek			Number 6839
Film Roll No.	Affix Contact Prints	Current Owner's Address: 6839 Cedar Street			
Negative No.		Legal Description: Lot 6, Block 2, Aetna Park Subdivision of the N.W. 1/4 of S 27, T 7 N, R 21 E, City of Wauwatosa,			
Facade Orient.					

Original Name & Use:	Source	Previous Owners	Dates	Uses	Source	Town
2 H.R. Davis home	A					7 N
Dates of Construction/Alteration 1924	A					21 E
Architect and/or Builder: Arnold F. Meyer & Company, Inc.	A					27

3 <u>Architectural Significance</u> <input type="radio"/> Represents work of a master <input type="radio"/> Possesses high artistic values <input checked="" type="radio"/> Represents a type, period, or method of construction <input type="radio"/> Engineering <input type="radio"/> None	4 <u>Historical Significance</u> <input type="radio"/> Assoc. with lives of significant persons <input type="radio"/> Assoc. with significant historical events <input type="radio"/> Assoc. with development of a locality <input type="radio"/> Other: _____ <input checked="" type="radio"/> None Period of significance: _____	Section 27
---	---	----------------------

Architectural Description and Significance: This 1 1/2 story Flagg System house has exterior walls of Tennessee quartzite. It is L shaped and faces north. Window and door openings are symmetrical. There is a steep gable composition roof. There are 3 1/2 pairs of ridge dormers, four shed dormers, and two chimneys with distinctive round openings. The glassed-in porch at the front entrance has a shed roof. The original garage with hip roof is attached to the house but a larger garage was built later which is not a significant part of this nomination. There is a stone fireplace in the living room Interior visited? <input checked="" type="radio"/> Yes <input type="radio"/> No (over)	Historical Background and Significance: 	Map Name Milwaukee Quadrangle
---	---	---

5 Sources of Information (Reference to Above) A Building Inspectors office City Wauwatosa	6 Representation in Previous Surveys <input type="radio"/> HABS <input type="radio"/> LDMK <input checked="" type="radio"/> WIHP <input type="radio"/> NRHP <input type="radio"/> other: _____
--	---

B	7 Condition <input checked="" type="radio"/> excellent <input type="radio"/> good <input type="radio"/> fair <input type="radio"/> poor <input type="radio"/> ruins
----------	---

C	8 District: _____ <input type="radio"/> pivotal <input type="radio"/> contributing <input type="radio"/> non-contributing	Map Code 7.5 minute
----------	---	-------------------------------

D	9 Opinion of National Register Eligibility date: _____ initials: _____ <input type="radio"/> eligible <input type="radio"/> not eligible <input type="radio"/> unknown <input type="radio"/> national <input type="radio"/> state <input type="radio"/> local
----------	---

and casement windows open inward. There is a partial basement and laundry room on the first floor. The bathroom floor is one step above the level of the hallway on the second floor. Storage space is in a walk-in attic on the second floor.

This house is architecturally significant because it is one of a group of stone masonry houses built by Arnold F. Meyer & Company, Inc. according to the construction methods of Ernest Flagg. It is also significant because it resembles the house illustrated on plate 20B in Flagg's book on small houses and the house at 1913 E. Olive Street.

